

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 07 Dec 2021

Preliminary Advice

Insured : GBC6640C

Vehicle No

TP Vehicle : GBC9606D
No

Accident Date : 23/11/2021

Make : FIAT DOBLO

Assignment Date : 25/11/2021

Date of : 26/11/2021

Est. Duration of : 5
Repair

Inspection

Inspection At : 1ST AUTO PRO PTE LTD (HQ)
15 KAKI BUKIT ROAD 4, #01-53
SINGAPORE 417808

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 18,441.20

Revised Amount :S\$ 7,050.39

Check Items (Estimated) :S\$ 0.00

Total :S\$ 7,050.39

Lump Sum Repair :S\$ 5,600.00

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.