

ASS. REC. BY: Marcus

REF:

CS/CT121011.995/4943**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBC P606D

at Workshop m/s

154 4th mo

of

Insured:

GBC 6640C

Policy No.

Claims No.

SNM21D206803/C2

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value:

\$20k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 812 988

Date / Time

Action / Instruction

Rep 8k.not 87012

Veh No:

GBC P606D

Yr Regn:

19/3/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

M / cargo

Make:

Fiat Doblo

c.c

1598

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

103572

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

2FA2630000 6141655

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapser

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

26/4/14

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 07/12 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: MER-TP

Lump Sum 48k (\$ 5600)

TOTAL

7/12/14 confirmed 4/5 \$ 5600 with Chris (Red \$12841.20, 70%)
 07/12/21 @ 3.03pm revised to Irene Tay via Merimen.



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 8718 6767 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD

3 ANSON ROAD #15-00

SPRINGLEAF TOWER

SINGAPORE 79909

ATTN: MOTOR CLAIMS DEPARTMENT

Takezhel. Attayev

*Not Approved
here
26/11/21
4/585600
5 days*

VEHICLE NO : GBC9606D

MAKE MODEL : FIAT DOBLO

REFERENCE : 1AP-202111-11

DOA : 23-Nov-21

CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
BONNET	1	\$ 1,080.00	✓ 1067.58
BONNET INSULATOR	1	\$ 166.00	X
BONNET HINGE LH / RH	2	\$ 338.00	✓ 135
BONNET LOCK	1	\$ 209.00	X
FRONT BUMPER	1	\$ 1,095.00	✓ 845.30
FRONT BUMPER SIDE RETAINER LH	1	\$ 184.00	✓ 68.00
FRONT BUMPER SIDE COVER LH	1	\$ 119.00	X
FRONT BUMPER REINFORCEMENT	1	\$ 459.00	✓
FRONT BUMPER LOWER GRILLE	1	\$ 361.00	X
FRONT RADIATOR GRILLE	1	\$ 339.00	X
FRONT RADIATOR GRILLE LOGO	1	\$ 149.00	X
FRONT TOW COVER	1	\$ 156.00	X
FRONT BUMPER SPONGE	1	\$ 119.00	✓ 117.00
FRONT FENDER LH	1	\$ 683.00	✓
FRONT FENDER INNER SHIELD LH	1	\$ 249.00	✓
FRONT SUPPORT PANEL	1	\$ 784.00	✓ 845.10
FRONT SUPPORT PANEL INNER GARNISH	1	\$ 133.00	X
FRONT HEADLAMP LH	1	\$ 1,349.00	✓ 658.70
BATTERY	1	\$ 568.00	X
ABS PUMP	1	\$ 1,189.00	X
ABS PUMP CABLE	1	\$ 317.00	X
FUEL BOX	1	\$ 746.00	✓ 485.00
WASHER TANK	1	\$ 309.00	X
AIRCON CONDENSER	1	\$ 1,280.00	X
RADIATOR ASSY	1	\$ 1,138.00	X
RADIATOR FAN ASSY	1	\$ 848.00	X
FRONT DOOR PANEL LH	1	\$ 1,401.00	X

\$ 15,768.00

LESS 10% \$ 1,576.80

SUBTOTAL \$ 14,191.20

BALANCE C/F \$ 14,191.20

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 14,191.20	
FRONT NUMBER PLATE	1	\$ 100.00	X

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD
 3 ANSON ROAD #15-00
 SPRINGLEAF TOWER
 SINGAPORE 79909
 ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : GBC9606D
MAKE MODEL : FIAT DOBLO
REFERENCE : 1AP-202111-11
DOA : 23-Nov-21
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT BUMPER CLIPS <i>new</i>	1	\$ 50.00	✓
FRONT FENDER INNER TRIM CLIPS <i>new</i>	1	\$ 50.00	✓
FRONT GRILLE CLIPS <i>17</i>	1	\$ 50.00	X
COOLANT <i>17</i>	1 BOT	\$ 100.00	X

SUBTOTAL \$ 350.00

BALANCE C/F \$ 14,541.20

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F \$ 14,541.20			

TO REMOVE AND REFIT ELECTRICAL WIRING AND TEST FOR PROPER FUNCTIONING	1	\$ 150.00	20
TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR	2	\$ 150.00	17X
TO REMOVE, REFIT AND TEST FOR PROPER FUNCTIONING - CONDENSER + TOP UP GAS	3	\$ 200.00	100
TO REMOVE, REFIT AND TEST FOR PROPER FUNCTIONING - RADIATOR + TOP UP COOLANT	4	\$ 200.00	11 X
TO REMOVE, REFIT AND TEST FOR PROPER FUNCTIONING - ABS PUMP	5	\$ 200.00	50
ALIGNMENT	6	\$ 100.00	60
TO TRANSFER DOOR COMPONENT FROM OLD TO NEW	7	\$ 200.00	11X
TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	8	\$ 100.00	90
TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	9	\$ 1,400.00	950
TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	10	\$ 1,200.00	800

SUBTOTAL \$ 3,900.00

GRAND TOTAL \$ 18,441.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-5422-61
 192
 P-4880-38
 S-N-100-00
 L-2070
 7050-38
 202
 2660