

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub, Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570C

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120
 Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Cecilia

Estimate : TP21-107

Date : 23/11/2021
 Vehicle Num. : SMG9074L
 Make/Model : Honda Vezel-2018
 Chassis/Eng# : RU11301910/L15B5551918
 Accident Date : 23/11/2021
 Claim No. :
 Reference :
 Policy No. : (02/01/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 pc	Rear Boot Lid <i>Distorted</i>		1,203.00 <i>1100.</i>
2.	1 pc	Rear Boot Lid Weatherstrip <i>ct</i>		171.70 <i>✓</i>
3.	1 pc	Rear Boot Lid Mechanism Lock <i>Damaged</i>		187.10 <i>✓</i>
4.	2 pcs	Rear Boot Hinge L/R <i>new</i>	68.00	136.00 <i>✓</i>
5.	2 pcs	Rear Boot Damper L/R <i>Best</i>	210.70	421.40 <i>✓</i>
6.	2 pcs	Rear Boot Lamp L/R <i>cracked</i>	378.10	756.20 <i>✓</i>
7.	1 pc	Rear Boot Lid No. Plate Lamp <i>no need</i>		48.50 <i>✓</i>
8.	1 pc	Rear No. Plate Garnish with Chrome Trim <i>cracked</i>		316.20 <i>✓</i>
9.	1 pc	Rear Boot Lid Honda Logo		58.60 <i>✓</i>
10.	1 pc	Rear Boot Lid Vezel Emblem <i>new</i>		98.00 <i>✓</i>
11.	1 pc	Rear Windscreen Moulding		161.85 <i>✓</i>
12.	1 pc	Rear Wiper Motor Assy <i>no need</i>		238.00 <i>✓</i>
13.	1 pc	Rear Boot Lid Inner Trim Board <i>cracked</i>		234.60 <i>✓</i>
14.	2 pcs	Rear Boot Lid Inner Top Trim Garnish L/R <i>new</i>	80.40	160.80 <i>✓</i>
15.	1 pc	Rear Boot Lid Inner Handle Holder <i>new</i>		30.05 <i>✓</i>
16.	1 pc	Rear Fender RH <i>Repair</i>		680.20 <i>✓</i>
17.	2 pcs	Rear Lamp Assy L/R <i>cracked</i>	628.30	1,256.60 <i>980.</i>
18.	2 pcs	Rear Bumper Side Holder L/R <i>new</i>	54.80	109.60 <i>✓</i>
19.	1 pc	Rear Lower Bumper Assy <i>Behind</i>		982.00 <i>765.</i>
20.	8 pcs	Rear Lower Bumper Clips <i>new</i>	4.50	36.00 <i>✓</i>
21.	2 pcs	Rear Bumper Reflector L/R <i>Rit cracked</i>	158.00	316.00 <i>158</i>
22.	1 pc	Rear End Panel <i>Distorted</i>		695.20 <i>545</i>
23.	1 pc	Rear End Panel Inner Top Garnish <i>Deformed</i>		125.30 <i>✓</i>
24.	1 pc	Rear Tyre Panel <i>Distorted</i>		820.30 <i>✓</i>
25.	1 pc	Rear Tyre Panel Trim Board Cover <i>Behind</i>		321.80 <i>255</i>
26.	1 pc	Rear Tools Sponge <i>cracked</i>		215.10 <i>✓</i>
27.	2 pcs	Rear Fender Inner Trim Garnish L/RH <i>cracked</i>	548.00	1,096.00 <i>790.40</i>
28.	2 pcs	Rear Fender Wheel Arc Trim Garnish L/R <i>cracked</i>	312.00	624.00 <i>397.40</i>
29.	1 pc	Rear Tyre Panel Under Shield Cover <i>Deformed</i>		181.50 <i>✓</i>

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub, Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120

Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Estimate : TP21-107

Date : 23/11/2021
 Vehicle Num. : SMG9074L
 Make/Model : Honda Vezel-2018
 Chassis/Eng# : RU11301910/L15B5551918
 Accident Date : 23/11/2021
 Claim No. :
 Reference :
 Policy No. : (02/01/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	8 pcs	Rear Tyre Panel Under Shield Cover Clips <i>New</i>	3.80	30.40 ✓
31.	1 pc	Rear Exhaust Silencer Box Assy with Bushing <i>Best.</i>		852.20 685
32.	1 pc	Rear Door Mechanism Lock RH <i>Free new</i>		123.50 x
33.	1 pc	Rear Axle Beam Assy		1,645.90 x.
34.	2 pcs	Rear Lamp Panel L/R <i>Peris</i>	159.10	318.20 +.
35.	1 pc	Frt Bumper <i>Delivered</i>		798.00 ✓
36.	2 pcs	Frt Bumper Side Holder L/R <i>New</i>	35.00	70.00 ✓
37.	1 pc	Frt Bumper Reinforcement <i>Dented</i>		598.00 395
38.	1 pc	Frt Bumper Lower Air Grille <i>Crackd.</i>		186.50 ✓
39.	1 pc	Frt Lower Bumper Extension <i>ton</i>		394.50 ✓
40.	1 pc	Frt Grille Assy <i>Crackd.</i>		480.00 ✓
41.	1 pc	Frt Grille Chrome Trim <i>Crackd.</i>		498.70 ✓
42.	1 pc	Frt Grille Honda Logo <i>New</i>		55.00 ✓
43.	2 pcs	Headlamp Assy L/R <i>Crackd</i>	1,893.80	3,787.60 ✓
44.	2 pcs	Headlamp Bracket L/R <i>Crackd</i>	68.50	137.00 ✓
45.	2 pcs	Frt Grille Bracket L/R <i>Crackd</i>	38.00	76.00 ✓
46.	2 pcs	Rear Shock Absorber L/R <i>New</i>	330.00	660.00 x
47.	1 pc	Rear Exhaust Aluminium Heat Shield <i>Crackd</i>		91.30 ✓
48.	2 pcs	Rear Side Bumper L/R <i>Delivered</i>	195.00	390.00 ✓
49.	1 pc	Rear Bumper Inner Side Shield RH <i>New</i>		103.80 x
List Total S\$:				22,978.80
20.00% Discount S\$:				4,595.76
				18,383.04
SPECIAL NETT ITEMS :				
1.	1 pc	Reverse Sensor <i>Damaged</i>		850.00 200
2.	1 set	Reverse Camera <i>New</i>		350.00 +
3.	1 pc	Windscreen Sealant <i>New</i>		40.00 ✓
4.	2 sets	Frt & Rear No. Plate w/frame <i>Damaged.</i>	45.00	90.00 ✓
Special Nett Total S\$:				830.00

17009.25
 13607.40

330

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub. Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120
 Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Estimate : TP21-107

Date : 23/11/2021
 Vehicle Num. : SMC9074L
 Make/Model : Honda Vezel-2018
 Chassis/Eng# : RU11301910/L15B5551918
 Accident Date : 23/11/2021
 Claim No. :
 Reference :
 Policy No. : (02/01/2022)

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

LABOUR :				
		To remove, rearrange electrical wirings, check lighting		150.00 60
		To remove, replace rear windscreen.		200.00 120
		To remove, reinstal upholstery, inner trim garnishes.		300.00 80
		To remove, reinstal rear exhaust to fascilitate repair.		200.00 80
		To remove, replace rear undercarriage parts.		380.00 x
		To remove, replace & transfer rear boot lid components.		280.00 80
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident		2,800.00 1800
		To putty and respray painting on affected area.		2,400.00 1400
		Labour Total SS :	3600	6,710.00

Total SS : 25,923.04
 =====

LKK Auto Consultants hence notify the Repairer Success United Pte Ltd

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Supplementary: 202.40
 total: 17,759.80
 CP (P)

Admin Lj
 P/P 24/11/21.
 14 Days.

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub. Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120
 Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Supplementary Estimate : TP21107S

Date : 23/11/2021
 Vehicle Num. : SMC9074L
 Make/Model : Honda Vezel-2018
 Chassis/Eng# : RU11301910/L15B5551918
 Accident Date : 23/11/2021
 Claim No. :
 Reference :
 Policy No. : (02/01/2022)

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

1.	2 pcs	LIST ITEMS : Rear Tyre Panel Trim Board Cover Lock L/R	126.50	253.00
		List TotalSS :		253.00
		20.00% Discount SS :		50.60
				202.40

Checked.

Adrian G
 26/11/21
HLG

Total SS : 202.40

SUCCESS UNITED PTE LTD