



FCI

Thevan@Lkhauto.com

82235769

26/11/21 1200

Lis after repair photo

6 days up

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Singapore 408974

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMANCE INVOICE

Vehicle number	GBB656Z
Make / Model	NISSAN CUBSTAR
Chassis number	JN1SC2F2470800273
Accident date	23/11/21
Reference	2111-24

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS

- 1 TAILGATE
- 1 TAILGATE LOWER MEMBER
- 3 TAILGATE LOWER HINGE
- 2 TAILGATE SIDE HINGE
- 2 TAILGATE SIDE LOCK
- 2 TAILGATE SIDE LOCK CATCH
- 1 TAILGATE EMBLEM - NISSAN
- 2 TAILGATE DAMPER
- 2 TAILLAMP
- 2 TAILLAMP PANEL
- 1 SPARE TYRE BRACKET
- 1 SPARE TYRE LOCK SCREW
- 1 SPARE TYRE TOP MEMBER
- 1 TOW HOOK
- 1 TOW HOOK BRACKET
- 1 FRONT BUMPER
- 1 FRONT BUMPER BRACKET
- 1 FRONT GRILLE
- 1 FRONT GRILLE EMBLEM - LOGO
- 2 FRONT HEADLAMP
- 2 FRONT HEADLAMP UNDER COVER
- 1 FRONT PANEL
- 1 FRONT PANEL EMBLEM
- 1 FRONT WIPER PANEL
- 1 FRONT WIPER LINK
- 1 FRONT CORNER PANEL LH
- 1 WING MIRROR ASSY LH
- 1 ROUND MIRROR ASSY LH

1605.56	✓ Def	1349
756.80	✓ DT	586.5
224.40	✓ DT	138
DT 149.60	✓ LH (RH) SUC	74.8
DT 400.40	✓ LH (RH) SUC	142.3
Cut 149.60	✓ LH (RH) SUC	74.8
97.90	✓ nec	
40.80	✓ DT S (RH) RH SUC	20.4
585.86	✓ CRU (LH) RH SUC	1000.00
183.80	✓ DT CLH	168.4
292.60	✓ X SUC	
25.90	✓ X SUC	
378.40	✓ X SUC	
134.20	✓ DT	
151.80	✓ X SUC	
1270.50	✓ Def	898.02
96.90	✓ DT	
737.66	✓ DIS	438.4
75.90	✓ nec	88.8
1139.60	✓ CRU	946.8
178.20	✓ DT CLH	88.1
1747.90	✓ Def	1412.7
70.40	✓ nec	88.8
578.05	✓ nec	340
151.80	✓ CRU	
479.93	✓ mi S	200
201.30	✓ SUC	
315.70	✓ SUC	

12221.46
Less 10%
1222.15
Subtotal
10999.31

PARTS REPLACEMENT - SPECIAL NETT ITEMS

- 1 REAR NUMBER PLATE
- 1 FLOOR WOODEN BOARD
- 1 TAILGATE STICKER - 70KM
- 1 TAILGATE STICKER - 13PAX
- 1 FRONT NUMBER PLATE
- 1 FRONT GRILLE CLIP

Δ 80.00	✓ nec	40
cut 800.00	✓ nec	250
Δ 50.00	✓ nec	30
Δ 50.00	✓ nec	30
Δ 80.00	✓ nec	40
Δ 30.00	✓ nec	20

Subtotal
1090.00

LABOUR AND MISCELLANEOUS CHARGES

- 1 CHECK WIRING AND LIGHTING SYSTEM
- 2 REMOVE AND REPLACE TAILGATE FROM OLD TO NEW
- 3 REMOVE AND REPLACE REAR FLOOR WOODEN BOARD
- 4 PANEL BEATING ON AFFECTED AREAS
- 5 SPRAY PAINTING ON AFFECTED AREAS
- 6 APPLY ANTI-RUST ON AFFECTED AREAS

80.00	✓ 50	
150.00	✓ 60	
200.00	✓ 40	
1500.00	✓ 1000	
1500.00	✓ 850	
150.00	✓ 40	

Subtotal
3580.00
Granttotal
15669.31

F: 7500