

Our Job Ref No : 305495618

Date : 29/11/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Thevan

Vehicle Reg No. : SHC7350H CCPL

24/11/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **TOKIO MARINE** --- **SKW3525G**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

\$0.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

\$1,700.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : MS. LOKE YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Thevan

Date : 30/11/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT DELGRO ENGINEERING

VEHICLE I SHC7350H
TOKIO MARINE
305495618

TYPE OF C: TP
SURVEY B: LKK/ THEVAN
DATE : 29/11/2021

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
REAR NUMBER PLATE WITH TRIM COVER	1	NETT	\$55.00	✓ CVA
REAR BUMPER LOWER CTR MOULDING	1		\$155.00	✓ DES
		TOTAL	\$210.00	

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305495618
 REGN NO : SHC7350H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 23.08.2018
 DATE/TIME IN : 24.11.2021 16:15
 ACCIDENT DATE : 24.11.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	0.00	0.00	0.00
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	0.00	0.00	0.00
0003	04-01-0104-2288-G	BEAM-RR BUMPER	1	0.00	0.00	0.00
0004	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	0.00	0.00	0.00
0005	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1	0.00	0.00	0.00
0006	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	0.00	0.00	0.00
0007	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	0.00	0.00	0.00

SUB-TOTAL : 0.00

JOB NATURE

0000 PB	LUMP SUM SHC7350H	1700.00
---------	-------------------	---------

SUB-TOTAL : 1,700.00

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 25 Nov 2021)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC7350H/25/11/2021 09:17**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	cut ✓ 459.40 FL
2	1		*REAR BUMPER CLIPS	20.00	0.00	net ✓ 22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	svc ✓ 451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	pr ✓ 394.80 FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	20.00	0.00	svc x 138.10 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH	20.00	0.00	svc x 138.10 FL
7	1		*REAR BUMPER TOWING COVER	20.00	0.00	svc x 98.80 FL
8	1		*REAR BUMPER REFLECTOR LAMP RH	20.00	0.00	svc x 41.45 FL
9	1		*ANTENNA ASSY SMARTKEY	20.00	0.00	svc x 40.50 FL
10	1		*REAR BUMPER FOG LAMP	20.00	0.00	svc x 201.50 FL
11	1		*REAR PANEL	20.00	0.00	svc x 532.00 FL
12	1		*REAR PANEL GARNISH	20.00	0.00	svc x 346.80 FL
13	1		*BOOTLID	20.00	0.00	svc x 2,480.40 FL
14	1		*BOOTLID HYUNDAI PLATE	20.00	0.00	svc x 24.30 FL
15	1		*EMBLEM HYBRID	20.00	0.00	svc x 24.30 FL
16	1		*EMBLEM - IONIQ	20.00	0.00	svc x 31.30 FL
17	1		*BOOTLID ADVERTISEMENT LOGO	7.00	0.00	net x 100.00 FN
18	1		*BOOTLID COMFORT TEL NO STICKER	7.00	0.00	net x 35.00 FN
19	1		*BOOTLID COMFORT LOGO STICKER	7.00	0.00	net x 30.00 FN
20	1		*BOOTLID COMFORT APP STICKER	7.00	0.00	net x 30.00 FN
21	1		*REAR BUMPER REVERSE SENSOR	7.00	0.00	cut ✓ 180.00 FN

F=Franchise part, L=ListItemDisc, N=NettItemDisc.

Sub Total (\$\$)	5,800.00
- List Item Discount on L Items (\$\$)	1,085.00
- Nett Item Discount on N Items (\$\$)	26.25
Total Parts (\$\$)	4,688.75

ComfortDelGro Engineering Pte Ltd/SHC7350H/25/11/2021 09:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Thuvan@lkhauto.com
82235769
26/11/21 1530
L/s after repair photo
on 2 days w/

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING		
2	SPRAY PAINTING CHARGE	New	350 800.00
3	CHK ALL LIGHTING	New	250 600.00
4	TUFF KOTE	New	30 60.00
5	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
		New	20 80.00

Gross Labour Cost (S\$)

1,600.00

ComfortDelGro Engineering Pte Ltd/SHC7350H/25/11/2021 09:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >