



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3314J

| Qty                                | Description of Parts                                 | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|------------------------------------------------------|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                                      |               |                           |                   |
| 1                                  | BOOT LID EMBLEM-HYBRID                               | NECESSARY     | 24.30                     | 24.30             |
| 1                                  | BOOT LID EMBLEM-IONIQ                                | NECESSARY     | 31.30                     | 31.30             |
| 1                                  | REAR BUMPER                                          | TORN          | 459.40                    | 459.40            |
| 1                                  | REAR BUMPER REINFORCEMENT                            | CRACKED       | 394.80                    | 394.80            |
| 2                                  | REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$138.10 | NOT NECESSARY | 276.20                    | -                 |
| 2                                  | REAR BUMPER REFLECTOR (LH/RH) @\$41.45               | NOT NECESSARY | 82.90                     | -                 |
| 1                                  | REAR BUMPER CENTRE MOULDING ASSY                     | DEFORMED      | 451.25                    | 451.25            |
| 1                                  | REAR BUMPER LOWER CENTRE MOULDING ASSY               | NOT NECESSARY | 155.00                    | -                 |
| 10                                 | REAR BUMPER CLIPS @\$2.20                            | NECESSARY     | 22.00                     | 22.00             |
| 1                                  | REAR BUMPER FOG LAMP                                 | NOT NECESSARY | 201.50                    | -                 |
| 1                                  | REAR BUMPER TOWING COVER                             | NOT NECESSARY | 98.80                     | -                 |
| 1                                  | REAR BUMPER SMART KEY ANTENNA                        | NOT NECESSARY | 40.50                     | -                 |
|                                    | LESS 20% DISCOUNT                                    |               | -447.59                   | -276.61           |
|                                    |                                                      |               | 1,790.36                  | 1,106.44          |
| <b><u>NETT ITEMS</u></b>           |                                                      |               |                           |                   |
| 1                                  | BOOT LID COMFORTDELGRO (N)                           | NECESSARY     | 35.00                     | 35.00             |
| 1                                  | BOOT LID 65521111 (N)                                | NECESSARY     | 35.00                     | 35.00             |
| 1                                  | BOOT LID APPS (N)                                    | NECESSARY     | 40.00                     | 40.00             |
| 1                                  | REAR BUMPER REVERSE SENSOR (N)                       | NOT WORKING   | 180.00                    | 180.00            |
| 1                                  | REAR NO PLATE W/TRIM COVER (N)                       | CRACKED       | 55.00                     | 55.00             |
|                                    | LESS 10% DISCOUNT                                    |               | -34.50                    | -34.50            |
|                                    |                                                      |               | 310.50                    | 310.50            |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                                      |               |                           |                   |
| 2                                  | REAR FENDER ADV STICKER RH/LH @\$100.00 (SN)         | NECESSARY     | 200.00                    | 200.00            |
| 1                                  | BOOTLID ADV STICKER (SN)                             | CUT           | 100.00                    | 100.00            |
| 1                                  | REAR BUMPER MAT (SN)                                 | NECESSARY     | 50.00                     | 50.00             |
|                                    |                                                      |               | 350.00                    | 350.00            |

Report Ref No. NS/INC21012002/T1ty3n2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

| Qty                                                                                             | Description of Parts         | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-------------------------------------------------------------------------------------------------|------------------------------|-----------|---------------------------|-------------------|
|                                                                                                 | <b>LABOUR</b>                |           |                           |                   |
|                                                                                                 | PANEL BEATING.               |           | 800.00                    | 525.00            |
|                                                                                                 | SPRAY PAINTING CHARGE.       |           | 600.00                    | 500.00            |
|                                                                                                 | REMOVE/REFIX REVERSE SENSOR. |           | 120.00                    | 30.00             |
|                                                                                                 |                              |           | 1,520.00                  | 1,055.00          |
|                                                                                                 | <b>GRAND TOTAL</b>           |           | <b>3,970.86</b>           | <b>2,821.94</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)<br/>(CONFIRMED)</b> |                              |           |                           | <b>2,250.00</b>   |

Report Ref No. NS/INC21012002/T1ty3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.