

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 29.10.2021 (Friday)

MODEL: Hyundai Ioniq

VEHICLE NO.: SHD3314J

INSURANCE: NTUC (L5)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Boot Lid Emblem-Hybrid	1		\$24.30 <i>ae</i>
	Boot Lid Emblem-Ioniq	1		\$31.30 <i>ae</i>
	Rear Bumper	1		\$459.40 <i>ae</i>
	Rear Bumper Reinforcement	1		\$394.80 <i>ae</i>
	Rear Bumper Reinforcement Bracket (LH/RH)	2	\$138.10	\$276.20 <i>ae</i>
	Rear Bumper Reflector (LH/RH)	2	\$41.45 <i>LH</i>	\$82.90 <i>ae</i>
	Rear Bumper Centre Moulding Assy	1		\$451.25 <i>ae</i>
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00 <i>ae</i>
	Rear Bumper Clips	10	\$2.20	\$22.00 <i>ae</i>
	Rear Bumper Fog Lamp	1		\$201.50 <i>ae</i>
	Rear Bumper Towing Cover	1		\$98.80 <i>ae</i>
	Rear Bumper Smart Key Antenna	1		\$40.50 <i>ae</i>
	SUB TOTAL		1383.05	\$2,237.95
	LESS 20%		1106.44	\$447.59
	DISCOUNTED TOTAL			\$1,790.36
	Boot Lid ComfortDelGro	1		\$35.00 <i>ae</i>
	Boot Lid 65521111	1		\$35.00 <i>ae</i>
	Boot Lid APPS	1		\$40.00 <i>ae</i>
	Rear Bumper Reverse Sensor	1		\$180.00 <i>ae</i>
	Rear No.Plate W/Trim Cover	1		\$55.00 <i>ae</i>
	S/NETT SUB		345	\$345.00
	LESS 10%			\$34.50
	S/NETT TOTAL			\$310.50
	Rear Fender Adv.Sticker RH/LH	2	\$100.00	\$200.00 <i>Nett ae</i>
	BootLid Adv.Sticker	1		\$100.00 <i>Nett ae</i>
	Rear Bumper Mat	1		\$50.00 <i>Nett ae</i>
	NETT TOTAL		350	\$350.00
	SPARE PARTS TOTAL			\$2,450.86
	Labour Charge			
	Panel Beating		1055	\$800.00 <i>525</i>
	Spray Painting Charge			\$600.00 <i>500</i>
	Remove/Refix Reverse Sensor			\$120.00 <i>30</i>
	TOTAL LABOUR		2856.44	\$1,520.00
	ESTIMATE TOTAL		2856.44	\$3,970.86

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Part prices are subject to confirmation

Part prices are subject to confirmation

Part prices are subject to confirmation

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Tanphn
89495749
WP 1/11/2020
c/s Resurvey after
report
furthering the estimate
2/3 days