

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	LONPAC INSURAI	NCE BHD	Ref:	CS3/LPC21007040/Buf3e2-1
	300 BEACH ROAD #17-04/07 THE CC) NCOURSESINGAPORE 199555	Date:	28/12/2021
			Code:	LPC2
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SMR 276Y	Veh. Inspected	SLM 8051P
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/21/21/VP05/024691	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	26/11/2021
2.	Vehicle Particulars & Condition			
	Make & Model	HONDA STREAM 1.8X	c.c	1799
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	RN61089412	Colour	BLACK
	Odometer	385601 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	POOR		
3.	Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	WEST LAKE	5 mm
	L/H Front Tyre	215/45 R17	WEST LAKE	5 mm
	R/H Rear Tyre	215/45 R17	WEST LAKE	5 mm
	L/H Rear Tyre	215/45 R17	WEST LAKE	5 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	23/06/2021	Inspection Date	28/06/2021
	Survey held at	MJE MOTOR	-	
		BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 16 Working Days			