

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No. EST0028302

Chia Wei-Hsiung Derek

Attn

Attn

Vehicle Model : Honda Shuttle

Vehicle No. SLN 5439U

Vehicle Model : Honda Shuttle

Accident on ... 24/11/2021

Page

Your ref.

Page

Your ref.

Job No.

Our ref.

Payment

Date

2 of 3

TP-GBH 6960Z MS FC

1 of 3

TP-GBH 6960Z MS FC

72364

21.11.19

2011/2021

26/11/2021

Not Authorized

Penalty B4pam

6 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Set	Supply of Parts:	200.00		200.00
1.00	Pc	Tailgate	867.00	20.00	693.60
1.00	Pc	Tailgate moulding c/w chrome moulding	363.20	20.00	290.56
1.00	Pc	Tailgate lock	174.00	20.00	139.20
1.00	Pc	Tailgate lamp RH	345.00	20.00	276.00
1.00	Pc	Tailgate inner handle	65.30	20.00	52.24
1.00	Pc	Tailgate weatherstrip	155.00	20.00	124.00
3.00	Pcs	Tailgate spoiler clips	5.50	20.00	13.20
1.00	Pc	Rear windscreen	876.90	20.00	701.52
1.00	Pc	Rear windscreen moulding	66.20	20.00	52.96
1.00	Pc	Rear logo emblem	49.40	20.00	39.52
1.00	Pc	Rear Shuttle emblem	68.60	20.00	54.88
1.00	Pc	Rear bumper	860.80	20.00	688.64
12.00	Pcs	Rear bumper clips	3.00	20.00	28.80
1.00	Pc	Rear end panel	434.50	20.00	347.60
1.00	Pc	Rear end panel LH	216.20	20.00	172.96
1.00	Pc	Rear end panel RH	216.20	20.00	172.96
1.00	Pc	Rear end panel top cover	238.00	20.00	190.40

Rear tool box 277.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

ESTIMATE

EST. No EST0028302

Chia Wei-Hsiung Derek

Page 2 of 3
Your ref. TP-GBH 6960Z MS FC
Job No. 72364
Our ref. 21.11.19
Payment
Date 26/11/2021

Attn

Vehicle No SLN 5439U

Vehicle Model : Honda Shuttle

Accident on ... 24/11/2021

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Special nett item:			
1.00		To straighten rear body including cutting	900.00		900.00
1.00	Set	Rear reversing sensor with installation of panel and renew of parts	200.00	na	200.00
		Labour & Misc:			
1.00		To spray paint	1,200.00		1,200.00
1.00		To remove + renew rear windscreen	140.00		140.00
1.00		To supply sealant	40.00		40.00
1.00		To remove + refit rear passenger seat, rear fender inner trims, carpet, etc	140.00		140.00
1.00		To transfer rear reversing camera	60.00		60.00
1.00		To transfer tailgate top spoiler	60.00		60.00
1.00		To transfer rear view camera	60.00		60.00
1.00		Tuff coat	60.00		60.00

Sub-Total 6,899.04
GST 7.00% 482.93
Total 7,381.97

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

NRIC No

Chia Wei-Hsiung Derek (Xie Weixiong, Derek)
SXXXX982J

Accident report SL0321BP0002

来發 (明記) 摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

SINGAPORE ACCIDENT STATEMENT ESTIMATE

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This form must be completed by the Policyholder and/or the Authorized Driver.

3. Any false reporting may be referred to the Police for investigation.

4. The issue and acceptance of this Form by insurance companies is not an admission of liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of the report in the centre and to copies of the report being made available aforesaid.

EST No EST0028302
Chia Wei-Hsiung Derek

Page 3 of 3
Your ref TP-GBH 6960Z MS.FG
Job No. 72364
Our ref 21.11.19
Payment
Date 26/11/2021

Attn Date of Submission 25/11/2021 12:01 (SGT)
Date of Accident 24/11/2021 16:50 (SGT)
Vehicle No SLN 5439U Woodlands Ave 12, Singapore
Vehicle Model Honda Shuttle at slip road from Gambas Avenue turning to Woodlands Avenue 12
Accident on 24/11/2021 Singapore

DETAILS OF OWN VEHICLE

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
----------	------	-------------	------------	------------	--------

1.00		To straighten rear body including cutting and welding, to knock dents on rear floor panel and renew of parts	900.00		900.00
------	--	--	--------	--	--------

1.00		To spray paint	1,200.00		1,200.00
------	--	----------------	----------	--	----------

VEHICLE PARTICULARS

Manufacturer Honda
Model Shuttle
Variant
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1500

INSURANCE COMPANY

Name of Insurance Company	Sub-Total	6,899.04
Type of Coverage	GST 7.00%	482.93
Fleet Policy	Total Comprehensive	S\$ 7,381.97

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Name of Driver Chia Wei-Hsiung Derek (Xie Weixiong, Derek)
NRIC No SXXXX982J