



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0949/2021/JT
DATE : 23-Nov-21
WIP : 54955

Veron.
\$6738.32

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 • Fax: 6880 4838

OWNER'S NAME : MR LIEW MUN KIONG
ADDRESS : 50 AMBER ROAD
#12-01
SINGAPORE 439888
TELEPHONE : HP +65 87818438
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210074983
VEHICLE NO : SMQ 8218 T
MODEL CODE : AUDI Q3 1.4 TFSI S
MODEL YEAR : 28/7/2021
ENGINE NO : CZD C41672
CHASSIS NO : WAUZZZF30M1128013
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Nov-21
PLACE OF ACCIDENT : ROCHOR ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMO 8218 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS OR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PRKING AID.	S/N \$ 480.00	✓✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000 ✓
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 4,000.00	1500. ✓ Bumper SSD Fender SSD wheel Arch x 2 = 200 x 2 = 400 = 400
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓✓
TOTAL LABOUR CHARGES		\$ 7,472.00	1500.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8218 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Repair torn</i>	1	\$ 1,335.00	<i>x</i> ✓ 1068
2	FRONT BUMPER FIXING PARTS	1	\$ 414.00	<i>x</i>
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 59.00	<i>x</i>
4	FRONT BUMPER TRIM - CENTER	1	\$ 356.00	<i>x</i>
5	FRONT BUMPER GRILLE - CENTER	1	\$ 217.00	<i>x</i>
6	FRONT PARKING AID SENSOR SUPPORT- LH	1	\$ 25.00	<i>x</i>
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 190.00	<i>x</i>
8	FRONT BUMPER SPOILER <i>Behind</i>	1	\$ 763.00	? 610
9	FRONT BUMPER BRACKET <i>new</i>	1	\$ 21.00	<i>x</i>
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 153.00	<i>x</i>
11	FRONT BUMPER TRIM - LH <i>new</i>	1	\$ 164.00	<i>x</i>
12	FRONT PARKING AID SENSOR SUPPORT OUTER - LH <i>new</i>	1	\$ 25.00	<i>x</i>
13	FRONT PARKING AID SENSOR <i>new</i>	1	TBC	<i>x</i>
14	FRONT FENDER - LH <i>Dented</i>	1	\$ 1,286.00	✓ 1028.80
15	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 63.00	<i>x</i>
16	FRONT FENDER BRACE - LH <i>new</i>	1	\$ 88.00	? <i>x</i>
17	FRONT FENDER BRACKET - LH <i>new</i>	1	\$ 32.00	? <i>x</i>
18	FRONT WHEEL ARCH TRIM COVER - LH / RH <i>LH out, RH in</i>	2	\$ 1,072.00	✓ 857.60
19	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 39.00	? <i>x</i>
20	HEADLIGHT MOUNTING - LH <i>new</i>	1	\$ 118.00	<i>x</i>
SUB TOTAL SPARE PARTS		:	\$ 6,420.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1193
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMO 8218 T

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	HEADLIGHT - LH	1	\$	5,589.00	X
22	LIFT CYLINDER - LH	1	\$	210.00	X
23	LIFT CYLINDER HOSE	1	\$	80.00	X
24	FRONT WHEEL HOUSING LINER - LH	1	\$	240.00	X
25	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS	1	\$	101.00	X
26	FRONT WHEEL HOUSING LINER LOWER COVER	1	\$	16.00	X
27	SUNDRIES	1	\$	300.00	? 1.92
TOTAL SPARE PARTS		:	\$	12,956.00	
TOTAL LABOUR CHARGES		:	\$	7,472.00	
GRAND TOTAL		:	\$	20,428.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *25/11/21.*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : *888* THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT