

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0949/2021/JT
DATE : 23-Nov-21
WIP : 54955

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days - ok - Jy - 13 Jan 22

OWNER'S NAME : MR LIEW MUN KIONG
ADDRESS : 50 AMBER ROAD
#12-01
SINGAPORE 439888
TELEPHONE : HP +65 87818438
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210074983
VEHICLE NO : **SMQ 8218 T**
MODEL CODE : AUDI Q3 1.4 TFSI S
MODEL YEAR : 28/07/2021
ENGINE NO : CZD C41672
CHASSIS NO : WAUZZZF30M1128013
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Nov-21
PLACE OF ACCIDENT : ROCHOR ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMQ 8218 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS OR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PRKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,000.00	\$ 1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 7,472.00	\$ 3,172.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8218 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,335.00	\$ 1,068.00
2	FRONT BUMPER FIXING PARTS	1	\$ 414.00	
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 59.00	
4	FRONT BUMPER TRIM - CENTER	1	\$ 356.00	
5	FRONT BUMPER GRILLE - CENTER	1	\$ 217.00	
6	FRONT PARKING AID SENSOR SUPPORT- LH	1	\$ 25.00	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 190.00	
8	FRONT BUMPER SPOILER	1	\$ 763.00	\$ 610.00
9	FRONT BUMPER BRACKET	1	\$ 21.00	
10	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 153.00	
11	FRONT BUMPER TRIM - LH	1	\$ 164.00	
12	FRONT PARKING AID SENSOR SUPPORT OUTER - LH	1	\$ 25.00	
13	FRONT PARKING AID SENSOR	1	TBC	
14	FRONT FENDER - LH	1	\$ 1,286.00	\$ 1,028.80
15	FRONT FENDER ATTACHMENT PARTS	1	\$ 63.00	
16	FRONT FENDER BRACE - LH	1	\$ 88.00	
17	FRONT FENDER BRACKET - LH	1	\$ 32.00	
18	FRONT WHEEL ARCH TRIM COVER - LH / RH	2	\$ 1,072.00	\$ 857.60
19	FRONT BUMPER GUIDE SECTION - LH	1	\$ 39.00	
20	HEADLIGHT MOUNTING - LH	1	\$ 118.00	
SUB TOTAL SPARE PARTS		:	\$ 6,420.00	\$ 3,564.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8218 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 3,564.40
21	HEADLIGHT - LH	1	\$ 5,589.00	
22	LIFT CYCLINDER - LH	1	\$ 210.00	
23	LIFT CYCLINDER HOSE	1	\$ 80.00	
24	FRONT WHEEL HOUSING LINER - LH	1	\$ 240.00	
25	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS	1	\$ 101.00	
26	FRONT WHEEL HOUSING LINER LOWER COVER	1	\$ 16.00	
27	SUNDRIES	1	\$ 300.00	\$ 1.92
TOTAL SPARE PARTS			\$ 12,956.00	\$ 3,566.32
TOTAL LABOUR CHARGES			\$ 7,472.00	\$ 3,172.00
GRAND TOTAL			\$ 20,428.00	\$ 6,738.32

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.