



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0948/2021/JT
DATE : 22-Nov-21
WIP : 54931

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/11/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

11-Jan-22

OWNER'S NAME : MR GWEE SIONG MONG
ADDRESS : 25 FERVALE ROAD
#19-23 HIGH PARK RESIDENCES
SINGAPORE 797639
TELEPHONE : HP +65 90171501
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100500708-04
VEHICLE NO : **SLL 1171 C**
MODEL CODE : AUDI A4 1.4 TFSI S
MODEL YEAR : 14/2/2017
ENGINE NO : CVN 024187
CHASSIS NO : WAUZZZF42HA067956
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Nov-21
PLACE OF ACCIDENT : SLIP ROAD AT SLE TO UPPER
THOMSON ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1171 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGNIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$	2,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,002.00	\$	2,652.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1171 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,111.00	\$ 1,688.80
2	FRONT BUMPER FIXING PARTS	1	TBC	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	
4	FRONT BUMPER GRILLE CENTER	1	\$ 196.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 210.00	
6	FRONT AIR GUIDE - LH / RH	2	\$ 126.00	
7	FRONT RADIATOR GRILLE	1	\$ 1,152.00	\$ 921.60
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 135.00	
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 124.00	
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 845.00	
11	FRONT BUMPER TOP COVER	1	\$ 127.00	
12	FRONT BUMPER GUIDE SECTION - LH	1	\$ 36.00	
13	CAUTION STICKER	1	\$ 14.00	
14	AIR COND STICKER	1	\$ 8.00	
15	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 137.00	
16	FRONT BUMPER SUPPORT- LH / RH	2	\$ 58.00	
17	HORN - LH	1	\$ 126.00	
18	HORN BRACKET - LH	1	\$ 29.00	
19	BONNET	1	\$ 3,246.00	\$ 2,596.80
20	BONNET ATTACHEMENT PARTS	1	\$ 412.00	
SUB TOTAL SPARE PARTS			\$ 9,163.00	\$ 5,207.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1171 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 5,207.20
21	BONNET HINGE - LH / RH	2	\$ 610.00	
22	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 84.00	\$ 65.68
23	BONNET STRIKER - LH	1	\$ 50.00	
24	BONNET LOCK	1	\$ 214.00	
25	BONNET BOWDEN CABLE CENTER - INNER / OUTER	2	\$ 116.00	
26	BONNET RELEASE LEVER	1	\$ 14.00	
27	PLENUM CHAMBER	1	\$ 97.00	
28	FRONT WHEEL HOUSING LINER - LH	1	\$ 240.00	
29	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS	1	TBC	
30	FRONT WHEEL SPOILER	1	\$ 73.00	
31	FRONT SPOILER - LH	1	\$ 35.00	
32	HEADLIGHT - LH	1	\$ 7,693.00	
33	LIFT CYCLINDER	1	\$ 210.00	
34	LIFT CYCLINDER HOSE	1	\$ 93.00	
35	RADIATOR AIR GUIDE INNER - LH	1	\$ 28.00	
36	RADIATOR AIR GUIDE OUTER - LH	1	\$ 12.00	
37	RADIATOR AIR GUIDE UPPER	1	\$ 16.00	
38	OUTSIDE TEMPEARATURE SENSOR BRACKET	1	\$ 19.00	
39	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
40	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 19,177.00	\$ 5,332.88
TOTAL LABOUR CHARGES			\$ 5,002.00	\$ 2,652.00
GRAND TOTAL			\$ 24,179.00	\$ 7,984.88

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-28/12/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT