

ASS. REC. BY: *marcus*REF: *CS/EG/21012018/U4F3***ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

*Dep 1.3.**2-15 yrs. Sale.**23/1/24 confirmed L/S @ 500 w. Raymond*Veh No: *FBL 8814D*Yr Regn: *03/05/17*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Bm / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS ___ \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197002288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 39564

Customer :

ERGO INSURANCE PTE LTD
302 ORCHARD ROAD
#09-01 TIONG BUILDING
SINGAPORE 238862

DATE : 17/11/2021
CLAIM NO. : 11822
POLICY NO. : MC/00914410
FROM : RAYMOND

VEHICLE NO. : FBL8814D
MAKE/MODEL : YAM / YBR125

not Authorized
26/11/21
2/s \$500
take photo after up
3 days

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER METER P/N: 49999 - (REPORTED BY MECHANIC)	<i>CR</i> REPLACE	1.00	\$23.00 ✓	23.00
2	CRASH BAR P/N: 35878 - (REPORTED BY MECHANIC)	<i>DD</i> REPLACE	1.00	\$203.00 ✓	203.00
3	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	<i>NN</i> REPLACE	1.00	\$14.00 X	14.00
4	HEADLAMP ASSY P/N: 43129 - (REPORTED BY MECHANIC)	<i>Sc 2</i> REPLACE	1.00	\$147.00 ✓	147.00
5	HOLDER CABLE P/N: 26470 - (REPORTED BY MECHANIC)	<i>11</i> REPLACE	1.00	\$6.00 X	6.00
6	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	<i>11</i> Supply/Install	5.00	\$63.00 200	315.00
7	LAMP SIGNAL FRONT LH P/N: 43433 - (REPORTED BY MECHANIC)	<i>11</i> REPLACE	1.00	\$21.00 X	21.00
8	LAMP SIGNAL REAR LH P/N: 44190 - (REPORTED BY MECHANIC)	<i>11</i> REPLACE	1.00	\$16.00 X	16.00
9	LAMP SIGNAL REAR RH P/N: 44191 - (REPORTED BY MECHANIC)	<i>11</i> REPLACE	1.00	\$21.00 X	21.00

*39564 *

102

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
10	LEVER BRAKE P/N: 26343 - (REPORTED BY MECHANIC)	n/c scr REPLACE	1.00	\$19.00	X 19.00
11	LEVER CLUTCH P/N: 52644 - (REPORTED BY MECHANIC)	n/c REPLACE	1.00	\$19.00	X 19.00
12	MIRROR RH P/N: 58187 - (REPORTED BY MECHANIC)	n/c cur REPLACE	1.00	\$35.00	X 35.00
13	MUDGUARD FRONT (RED) P/N: 42220 - (REPORTED BY MECHANIC)	one REPLACE	1.00	\$49.00	/ 49.00
14	PIPE EXHAUST ASSY P/N: 68440 - (REPORTED BY MECHANIC)	n/c REPLACE	1.00	\$399.00	X 399.00
15	PROTECTOR EXHAUST P/N: 68051 - (REPORTED BY MECHANIC)	n/c cur REPLACE	1.00	\$77.00	X 77.00
16	PROTECTOR EXHAUST CAP P/N: 68052 - (REPORTED BY MECHANIC)	n/c cur REPLACE	1.00	\$49.00	X 49.00
17	REPAIR ON FORK ALIGNMENT - (REPORTED BY MECHANIC)	su Repair	1.00	\$95.00	X 95.00
18	RUBBER FOOTREST FRONT P/N: 26136 - (REPORTED BY MECHANIC)	n/c REPLACE	2.00	\$14.00	X 28.00
19	STEERING CONE SET P/N: 41793 - (REPORTED BY MECHANIC)	n/c REPLACE	1.00	\$66.00	X 66.00
20	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	n/c REPLACE	1.00	\$19.00	10 19.00
21	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH	+ 1.00	\$55.00	35 55.00	
22	VISOR P/N: 43130 - (REPORTED BY MECHANIC)	one REPLACE	1.00	\$30.00	/ 30.00

SUB TOTAL

GST @ 7 %

\$1,706.00

\$119.42

GRAND TOTAL (SGD)

\$1,825.42

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

50% deposit required before ordering of parts. (used parts) during resurvey

Validity: 30 days

*39564 *

Acknowledged by Repairer

Signature:

Date:

bizSAFE₃CERT NO.: 2002-14383
ISO 9001:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*39564 *

bizSAFE₃