

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9065M**AAD2111-139**

Not Notified
Recovery Bk paint
85829.10

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

25 NOV 2021**SHD9065M**

JTDKB3FU103077294

TOYOTA

PRIUS

23/11/2021

AIG

12/12/2018

	PART
1	COVER, REAR BUMPER
1	GUARD, REAR BUMPER, CENTER
1	COVER, REAR BUMPER, LOWER
1	FILLER, REAR BUMPER EXTENSION, LH
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	RETAINER, REAR BUMPER SIDE, LH
1	COVER, FLOOR UNDER, NO.1 (LH)
1	COVER, REAR FLOOR (CTR)
1	LENS AND BODY, REAR LAMP, LH
1	LENS & BODY, REAR COMBINATION LAMP, LH
1	COVER, DECK TRIM, REAR
1	PANEL SUB-ASSY, BODY LOWER BACK
1	PANEL SUB-ASSY, BACK DOOR
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	STAY ASSY, BACK DOOR, LH
1	STAY ASSY, BACK DOOR, RH
1	HINGE ASSY, BACK DOOR, LH
1	HINGE ASSY, BACK DOOR, RH

	LIST	
\$	<i>BT/CTR</i> 442.60	✓
\$	<i>Bt</i> 576.30	✓
\$	<i>Sm</i> 15.40	X
\$	<i>mg CTR</i> 123.70	✓
\$	<i>Bt</i> 332.70	✓
\$	<i>D/S</i> 116.50	✓
\$	<i>Sm</i> 175.10	X
\$	<i>Sm</i> 229.90	X
\$	<i>Sm</i> 502.00	X
\$	<i>ORA fm</i> 443.30	X
\$	<i>Sm</i> 126.70	X
\$	<i>Bt</i> 650.30	✓
\$	<i>Bt</i> 1,147.80	✓
\$	<i>CM</i> 925.60	✓
\$	<i>Sm</i> 242.50	X
\$	<i>R</i> 242.50	X
\$	<i>R</i> 61.00	X
\$	<i>R</i> 61.00	X
TOTAL	\$ 6,414.90	
25%	\$ 1,603.73	
	\$ 4,811.18	

Special Nett

1	PARKING AID
1	REAR FLOOR COVER CLIP
1	REAR LOWER BUMPER CLIP

\$	<i>Net</i> 700.00	<i>200sm</i>
\$	<i>nn</i> 60.00	X
\$	<i>nn</i> 65.00	<i>50sm</i>

Trans-cab Auto Services Pte Ltd**AAD2111-139**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9065M

- | | | | | |
|---|------------------------------|----|--------|------|
| 1 | REAR BUMPER CLIP | \$ | 60.00 | 50\$ |
| 1 | BOOT STICKER TRANSCAB | \$ | 100.00 | 30\$ |
| 1 | BOOT STICKER TEL.NO | \$ | 100.00 | 30\$ |
| 2 | WINDSCREEN SEALANT | \$ | 150.00 | 80\$ |
| 1 | WINDSCREEN MOULDING | \$ | 200.00 | ✓ |
| 1 | WINDSCREEN INNER SPONGE SEAL | \$ | 130.00 | 30\$ |

TOTAL**\$ 1,565.00****TOTAL PARTS****\$ 6,376.18****LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 60\$

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 600\$

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 880\$

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 30\$

To Check Electrical Lighting Concerned.

\$ 170.00 20\$

TOTAL**\$ 3,590.00****Over All Total****\$ 9,966.18****(PART-BY-PART) Repair Days**~~20 days~~

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: