

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 7107B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	DENTED	772.50	772.50
1	LOGO EMBLEM	NECESSARY	50.80	50.80
1	VIOS EMBLEM	NECESSARY	58.00	58.00
1	E EMBLEM	NECESSARY	35.50	35.50
1	BOOTLID LH REFLECTOR	CUT	233.00	233.00
1	BOOTLID LOCK	NOT NECESSARY	399.50	-
1	BOOTLID W/STRIP	NOT NECESSARY	175.80	-
1	LH TAILLAMP	CUT	360.90	360.90
1	REAR BUMPER	DEFORMED	595.00	595.00
1	REAR BUMPER LH RETAINER	NOT NECESSARY	154.80	-
1	REAR BUMPER LH HOLDER	DAMAGED	110.00	110.00
6	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	REAR BUMPER LH REFLECTOR	CRACKED	93.90	93.90
1	REAR BUMPER REINFORCEMENT	DENTED	322.30	322.30
1	REAR LH FENDER	TO REPAIR SEE LABOUR	907.50	-
1	END PANEL	TO REPAIR SEE LABOUR	742.30	-
1	END PANEL INNER GARNISH	NOT NECESSARY	278.30	-
	LESS 25% DISCOUNT		-1,330.03	-665.48
			3,990.07	1,996.42
	SPECIAL NETT ITEMS			
1	REAR NO PLATE (SN)	NOT NECESSARY	40.00	-
1	REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
			290.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR LH FENDER AND END PANEL.		1,400.00	700.00
	SPRAY PAINTING.		1,600.00	1,200.00
	WIRING.		30.00	30.00

Report Ref No. CS/SMO21012021/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,300.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	RUST PROOFING.		80.00	60.00
			3,110.00	1,990.00
	GRAND TOTAL		7,390.07	4,186.42

Report Ref No. CS/SMO21012021/Aqf3n2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.