



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21012027/Utf3n2	
			Date: 06/12/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 750M	Veh. Inspected	SLK 1523B
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/21/21/VC05/025191	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	26/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALPHARD (A)	c.c	2493
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	AGH300088142	Colour	SILVER
	Odometer	67334 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 ZR18	TOURADOR	6 mm
	L/H Front Tyre	225/50 ZR18	TOURADOR	6 mm
	R/H Rear Tyre	225/50 ZR18	TOURADOR	6 mm
	L/H Rear Tyre	225/50 ZR18	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/11/2021	Inspection Date	26/11/2021
	Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	