

**Indeco**

No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES &amp; EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

**ACCIDENT REPAIR ESTIMATES**

Our Ref: TP / SMD2404E

Type of Claim : TPVehicle No. : SMD2404EMake & Model : BLUECARYear of Manufacture : 2017Chassis No. : VL4BCEB4RJ003275Ins Company : AIG ASIA PACIFIC  
INSURANCE PTE LTDEngine No. : Excess : Policy No. : SD21V00611/VPZ/R01Date of Accident : 25/11/2021Time of Accident : 00:00:00Suggested Days of Repair : 7Case Owner : BLUECAR EAST ASIA PTE LTDTP Vehicle No. : SKU8789P**Repair Estimates**Parts (a) Cost / List Price Items \$ 7,151.00Plus/Less 20.0% \$ 1,430.20Total of Cost / List \$ 8,581.20(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 90.00Total Parts Cost (Appendix A) \$ 8,671.20Labour (Appendix B) \$ 2,470.00Total Repair Cost \$ 11,141.20

The above total will be subjected to 7% G.S.T.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Tanfikh 97495749 / 62563561Company : LKKSurvey conducted on : 29/11/21 at Remarks By Surveyor : tanfikh @lkkauto.com(a) The repair of this vehicle is authorized / is not authorized until further notice. To check repair 4/5 star plp(b) Recommended Days of Repair : 4 day(s) Resurvey before/after paint(c) Resurvey : Required / Not Required(d) Excess : \$ (e) Signature of surveyor : [Signature]Date: 29/11/21

**Indeco**

VEHICLES &amp; EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

**FINALIZATION REPAIR COST DETAILS**

Vehicle No	: SMD2404E	Case Owner	: BLUECAR EAST ASIA PTE LTD
Make & Model	: BLUECAR	Year Manufacture	: 2017
Chassis No	: VL4BCEB4RJT003275	Engine No	: 0
Date & Time	:	Supplier	:
Order By	:	Type of Claim	: TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT BUMPER	1	\$ 2,073.00	\$ 2,073.00	de ✓		
2	FRONT BUMPER CLIPS	10	\$ 2.00	\$ 20.00	de ✓		
3	FRONT REINFORCEMENT	1	\$ 340.00	\$ 340.00	?		
4	FRONT REINFORCEMENT BRACKET	2	\$ 280.00	\$ 560.00	?		
5	FRONT BUMPER SPONGE WITH CLIPS	1	\$ 225.00	\$ 225.00	?		
6	REAR BUMPER	1	\$ 1,950.00	\$ 1,950.00	de ✓		
7	REAR BUMPER REINFORCEMENT	1	\$ 275.00	\$ 275.00	?		
8	REAR BUMPER REINFORCEMENT BRACKET LH	1	\$ 60.00	\$ 60.00	?		
9	REAR BUMPER REINFORCEMENT BRACKET RH	1	\$ 60.00	\$ 60.00	?		
10	REAR BUMPER REFLECTOR RH	1	\$ 173.00	\$ 173.00	one ✓		
11	REAR BUMPER REFLECTOR LH	1	\$ 172.00	\$ 172.00	X		
12	REAR END PANEL	1	\$ 655.00	\$ 655.00	Rp		
13	CHARGER AIR INLET	1	\$ 172.00	\$ 172.00	X		
14	CHARGER AIR INLET GASKET	1	\$ 8.00	\$ 8.00	X		
15	REAR AIR VENT (BOOT/TRUNK)	2	\$ 46.00	\$ 92.00	X		
16	REAR NUMBER PLATE LAMP	2	\$ 158.00	\$ 316.00	24-? RH dg ✓		
17	NUMBER PLATE WITH CASING	2			bt ✓		\$ 90.00
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL**      \$ 6,649.00    \$ 7,151.00    \$ -    \$ -    \$ 90.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

## Labour

Vehicle No.	SMD2404E
Make & Model	BLUECAR

Case	Owner	Year of Manufacture
1	...	...
2	...	...
3	...	...
4	...	...
5	...	...
6	...	...
7	...	...
8	...	...
9	...	...
10	...	...
11	...	...
12	...	...
13	...	...
14	...	...
15	...	...
16	...	...
17	...	...
18	...	...
19	...	...
20	...	...
21	...	...
22	...	...
23	...	...
24	...	...
25	...	...
26	...	...
27	...	...
28	...	...
29	...	...
30	...	...
31	...	...
32	...	...
33	...	...
34	...	...
35	...	...
36	...	...
37	...	...
38	...	...
39	...	...
40	...	...
41	...	...
42	...	...
43	...	...
44	...	...
45	...	...
46	...	...
47	...	...
48	...	...
49	...	...
50	...	...
51	...	...
52	...	...
53	...	...
54	...	...
55	...	...
56	...	...
57	...	...
58	...	...
59	...	...
60	...	...
61	...	...
62	...	...
63	...	...
64	...	...
65	...	...
66	...	...
67	...	...
68	...	...
69	...	...
70	...	...
71	...	...
72	...	...
73	...	...
74	...	...
75	...	...
76	...	...
77	...	...
78	...	...
79	...	...
80	...	...
81	...	...
82	...	...
83	...	...
84	...	...
85	...	...
86	...	...
87	...	...
88	...	...
89	...	...
90	...	...
91	...	...
92	...	...
93	...	...
94	...	...
95	...	...
96	...	...
97	...	...
98	...	...
99	...	...
100	...	...

BLUECAR  
EAST ASIA  
PTE LTD  
2017

[illegible]

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*