

Indeco

No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SMD2404E

Type of Claim : TPVehicle No. : SMD2404EMake & Model : BLUECARYear of Manufacture : 2017Chassis No. : VL4BCEB4RJT003275Ins Company : AIG ASIA PACIFIC
INSURANCE PTE LTDEngine No. : Excess : Policy No. : SD21V00611/VPZ/R01Date of Accident : 25/11/2021Time of Accident : 00:00:00Suggested Days of Repair : 7Case Owner : BLUECAR EAST ASIA PTE LTD**Repair Estimates**TP Vehicle No. : SKU8789PParts (a) Cost / List Price Items \$ 7,151.00Plus/Less 20.0% ^{15%} \$ 1,430.20Total of Cost / List \$ 8,581.20(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 90.00Total Parts Cost (Appendix A) \$ 8,671.20Labour (Appendix B) \$ 2,470.00Total Repair Cost \$ 11,141.20

Parts \$5,277.00

+15% \$ 791.55

SN \$ 90.00

L/B \$1,100.00

\$7,258.55

L/S \$5,800.00

4 days #

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Tanfikh 97495749/62563561Company : LKKSurvey conducted on : 29/11/21 at Remarks By Surveyor : Tanfikh @ lkkauto.com

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ (e) Signature of surveyor : [Signature] Date: 29/11/21To check repair 4/5th p/p
Resurvey before/after
permit



VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

FINALIZATION REPAIR COST DETAILS

Vehicle No : SMD2404E Case Owner : BLUECAR EAST ASIA PTE LTD

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RJT003275 Engine No : 0

Date & Time : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT BUMPER	1	\$ 2,073.00	\$ 2,073.00	de ✓		
2	FRONT BUMPER CLIPS	10	\$ 2.00	\$ 20.00	na ✓		
3	FRONT REINFORCEMENT	1	\$ 340.00	\$ 340.00	?	bt ✓	
4	FRONT REINFORCEMENT BRACKET	2	\$ 280.00	\$ 560.00	?		xnn
5	FRONT BUMPER SPONGE WITH CLIPS	1	\$ 225.00	\$ 225.00	?	de ✓	
6	REAR BUMPER	1	\$ 1,950.00	\$ 1,950.00	de ✓		
7	REAR BUMPER REINFORCEMENT	1	\$ 275.00	\$ 275.00	?		xnn
8	REAR BUMPER REINFORCEMENT BRACKET LH	1	\$ 60.00	\$ 60.00	?		xnn
9	REAR BUMPER REINFORCEMENT BRACKET RH	1	\$ 60.00	\$ 60.00	?		xnn
10	REAR BUMPER REFLECTOR RH	1	\$ 173.00	\$ 173.00	over ✓		
11	REAR BUMPER REFLECTOR LH	1	\$ 172.00	\$ 172.00	x		xnn
12	REAR END PANEL	1	\$ 655.00	\$ 655.00	Rp		XR
13	CHARGER AIR INLET	1	\$ 172.00	\$ 172.00	x	de ✓	
14	CHARGER AIR INLET GASKET	1	\$ 8.00	\$ 8.00	x	de ✓	
15	REAR AIR VENT (BOOT/TRUNK)	2	\$ 46.00	\$ 92.00	x		xnn
16	REAR NUMBER PLATE LAMP	2	\$ 158.00	\$ cra 316.00	RH ✓	RH ds ✓	
17	NUMBER PLATE WITH CASING	2			bt ✓		\$ 90.00
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 6,649.00 \$ 7,151.00 \$ - \$ - \$ 90.00 ✓

5,277.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR
EAST ASIA

Case Owner
Year of Manufacture

: PTE LTD

: 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1,100.00