

Indeco

No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SMD2404E

Type of Claim : TP

Vehicle No. : SMD2404E

Make & Model : BLUECAR

Year of Manufacture : 2017

Chassis No. : VL4BCEB4RJ003275

Ins Company : AIG ASIA PACIFIC
INSURANCE PTE LTD

Engine No. :

Excess :

Policy No. : SD21V00611/VPZ/R01

Date of Accident : 25/11/2021

Time of Accident : 00:00:00

Suggested Days of Repair : 7

Case Owner : BLUECAR EAST ASIA PTE LTD

Repair Estimates

TP Vehicle No. : SKU8789P

Parts (a) Cost / List Price Items \$ 7,151.00

Plus/Less ^{15%} 20.0% \$ 1,430.20

Total of Cost / List \$ 8,581.20

(b) Nett Price Items \$ -

Less \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 90.00

Total Parts Cost (Appendix A) \$ 8,671.20

Labour (Appendix B) \$ 2,470.00

Total Repair Cost \$ 11,141.20

Parts \$ 5,277.00

+ 15% \$ 791.55

SN \$ 90.00

L/B \$ 1,100.00

\$ 7,258.55

L/S \$ 5,800.00

4 days #

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Tanfikh 97495749 / 62563561

Company : LKK

Survey conducted on : 29/11/21 at

Remarks By Surveyor

tanfikh@lkkauto.com

(a) The repair of this vehicle is authorized / is not authorized until further notice.

To check repair 4/5 p/p

(b) Recommended Days of Repair : 4 day(s)

Resurvey before/after
permit

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : *[Signature]* Date: 29/11/21



VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

FINALIZATION REPAIR COST DETAILS

Vehicle No : SMD2404E Case Owner : BLUECAR EAST ASIA PTE LTD

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RJT003275 Engine No : 0

Date & Time : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT BUMPER	1	\$ 2,073.00	\$ 2,073.00	de ✓		
2	FRONT BUMPER CLIPS	10	\$ 2.00	\$ 20.00	NO ✓		
3	FRONT REINFORCEMENT	1	\$ 340.00	\$ 340.00	?	bt ✓	
4	FRONT REINFORCEMENT BRACKET	2	\$ 280.00	\$ 560.00	?		xnn
5	FRONT BUMPER SPONGE WITH CLIPS	1	\$ 225.00	\$ 225.00	?	de ✓	
6	REAR BUMPER	1	\$ 1,950.00	\$ 1,950.00	de ✓		
7	REAR BUMPER REINFORCEMENT	1	\$ 275.00	\$ 275.00	?		xnn
8	REAR BUMPER REINFORCEMENT BRACKET LH	1	\$ 60.00	\$ 60.00	?		xnn
9	REAR BUMPER REINFORCEMENT BRACKET RH	1	\$ 60.00	\$ 60.00	?		xnn
10	REAR BUMPER REFLECTOR RH	1	\$ 173.00	\$ 173.00	over ✓		
11	REAR BUMPER REFLECTOR LH	1	\$ 172.00	\$ 172.00	X		xnn
12	REAR END PANEL	1	\$ 655.00	\$ 655.00	Rp		XR
13	CHARGER AIR INLET	1	\$ 172.00	\$ 172.00	X	de ✓	
14	CHARGER AIR INLET GASKET	1	\$ 8.00	\$ 8.00	X	de ✓	
15	REAR AIR VENT (BOOT/TRUNK)	2	\$ 46.00	\$ 92.00	X		xnn
16	REAR NUMBER PLATE LAMP	2	\$ 158.00	\$ cra 316.00	RH ✓	RH ds ✓	
17	NUMBER PLATE WITH CASING	2			bt ✓		\$ 90.00
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 6,649.00 \$ 7,151.00 \$ - \$ - \$ 90.00 ✓

5,277.00

Indeco

VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Labour

Vehicle No. : SMD2404E
Make & Model : BLUECAR

Case Owner : BLUECAR EAST ASIA
Year of Manufacture : PTE LTD
2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	LABOUR TO REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	\$800.00	200
2	TO PUTTY AND RESPRAY FRONT BUMPER, BONNET AND AFFECTED AREAS	\$400.00	200
3	LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	\$600.00	300
4	TO PUTTY AND RESPRAY REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL AND AFFECTED AREAS	\$400.00	200
5	TO APPLY TUFF COATING	\$120.00	X nn
6	TO CHECK WIRING AND UPDATE SYSTEM	\$150.00	100
			1100
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		TOTAL \$	2,470.00

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1,100.00