

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012035/AEA3Q2**Date:** 16/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070016933
Claimant Vehicle No :	SJE3613S	Insured Vehicle No :	SMS2758E
Date of Loss:	25/11/2021	Nature of Claim:	TP
		Claim No:	7332923688SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE3613S	Engine No:	LF10529950
Make & Model:	MAZDA 5, 2.0 (A)	Chassis No:	JM6CR10F280304184
Reg. Date:	23/04/2008 (Man. Year: 2008)	Odometer:	137865 km
Colour:	Purple		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,979.04	3,052.88	1,926.16	38.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,870.00	1,440.00	1,430.00	49.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,849.04	4,492.88	3,356.16	42.76
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	7,849.04	3,600.00	4,249.04	54.13
+ GST 7.00/7.00% (S\$)	549.43	252.00	297.43	54.13
Nett Amount (S\$)	8,398.47	3,852.00	4,546.47	54.13
+ Car Rental (6.0 x S\$140.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,694.00		

INSPECTION

Date of Assignment:	25/11/2021	Kang Car Repairers Pte Ltd (HQ)
Date Inspected:	25/11/2021 Inspected At:	No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR LH	Dented	1,201.70 FL	*1,201.70 FL
2	1		*FRT DOOR GLASS REGULATOR LH	Cracked	421.20 FL	*421.20 FL
3	1		*FRT DOOR GLASS REGULATOR MOTOR LH	Not Necessary	587.60 FL	*- FL
4	1		*FRT DOOR CENTER MOULDING LH	Deformed	121.80 FL	*121.80 FL
5	1		*FRT DOOR INNER LOCK LH	Not Necessary	511.70 FL	*- FL
6	1		*FRT DOOR RUBBER LH	Not Necessary	122.30 FL	*- FL
7	1		*FRT DOOR INNER TRIM LH	Cracked	480.10 FL	*480.10 FL
8	1		*FRT DOOR TOP MOULDING LH	Not Necessary	123.60 FL	*- FL
9	2		*FRT DOOR FRAME STICKER LH	Necessary	91.40 FL	*91.40 FL
10	1		*REAR DOOR LH	Dented	1,198.60 FL	*1,198.60 FL
11	1		*REAR DOOR CENTER MOULDING LH	Deformed	111.40 FL	*111.40 FL
12	1		*REAR DOOR SIDE RUBBER LH	Necessary	101.70 FL	*101.70 FL
13	2		*REAR DOOR FRAME STICKERS	Necessary	88.20 FL	*88.20 FL
14	1		*REAR TYRE RIM LH	Not Necessary	850.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,011.30	3,816.10
- List Item Discount on L Items 20.00/20.00% (S\$)	1,032.26	763.22
Total Parts (S\$)	4,979.04	3,052.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS AND CUTTING/WELDING WORKS	New	1,200.00	500.00
2	TO SPRAY PAINTING	New	1,200.00	700.00
3	TO REPLACE DOOR TRIM	New	120.00	0.00
4	TO TRANSFER FRONT LH DOOR FITTINGS	New	100.00	80.00
5	TO TRANSFER REAR LH DOOR FITTINGS	New	100.00	80.00
6	TO CHECK WIRING	New	50.00	30.00
7	TO SPRAY TUFF COAT	New	100.00	50.00
Gross Labour Cost (\$)			2,870.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >