

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST.201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY #07-16  
 AIG BUILDING, SINGAPORE 079120  
 TEL: 64193000 FAX: 68357416  
 ATTN: Motor Claim Department

Estimate No: EST2100314  
 Date: 26 Nov 2021  
 Veh Reg No: SJE3613S  
 Make/Model: MAZDA 5  
 Chasis No: JM6CR10F280304184  
 Reg. Date: 23/04/2008  
 Your Ref No: SMS2758E

Claim Type: Third Party  
 Accident Date: 25/11/2021  
 TP Veh Reg No: SMS2758E

*Cecilin*

## Estimate Repair Cost to Vehicle No :SJE3613S

Quantity	Description	List Price	Amount
		SS	SS
<b>List Price</b>			
1	1 PC FRT DOOR LH <i>Dented</i>	1,201.70	✓
2	1 PC FRT DOOR GLASS REGULATOR LH <i>cruld</i>	421.20	✓
3	1 PC FRT DOOR GLASS REGULATOR MOTOR LH <i>new</i>	587.60	x
4	1 PC FRT DOOR CENTER MOULDING LH <i>deld</i>	121.80	✓
5	1 PC FRT DOOR INNER LOCK LH <i>new</i>	511.70	x
6	1 PC FRT DOOR RUBBER LH <i>new</i>	122.30	x
7	1 PC FRT DOOR INNER TRIM LH <i>cruld</i>	480.10	✓
8	1 PC FRT DOOR TOP MOULDING LH <i>new</i>	123.60	x
9	2 PCS FRT DOOR FRAME STICKER LH <i>new</i>	91.40	✓
10	1 PC REAR DOOR LH <i>Dented</i>	1,198.60	✓
11	1 PC REAR DOOR CENTER MOULDING LH <i>deld</i>	111.40	✓
12	1 PC REAR DOOR SIDE RUBBER LH <i>new</i>	101.70	✓
13	2 PCS REAR DOOR FRAME STICKERS <i>new</i>	88.20	✓
		5,161.30	
	Less 20%	1,032.26	4,129.04
<b>Special Net</b>			
14	1 PC REAR TYRE RIM LH <i>new</i>	850.00	x
		850.00	850.00
<b>Labour</b>			
15	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS AND CUTTING/WELDING WORKS.	1,200.00	500
16	1 TO SPRAY PAINTING	1,200.00	700
17	1 TO REPLACE DOOR TRIM	120.00	x
18	1 TO TRANSFER FRONT LH DOOR FITTINGS	100.00	80
19	1 TO TRANSFER REAR LH DOOR FITTINGS	100.00	80
20	1 TO CHECK WIRING	50.00	30
		2,770.00	2,770.00

*To spray tuff coat.*

*100 50*

*1740*

*3816.10*

*3052.88*

*2959.12*

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
AIG BUILDING, SINGAPORE 079120  
TEL: 64193000 FAX: 68357416  
ATTN: Motor Claim Department

Claim Type: Third Party  
Accident Date: 25/11/2021  
TP Veh Reg No: SMS2758E

Estimate No: EST2100314  
Date: 26 Nov 2021  
Veh Reg No: SJE3613S  
Make/Model: MAZDA 5  
Chasis No: JM6CR10F280304184  
Reg. Date: 23/04/2008  
Your Ref No: SMS2758E

## Estimate Repair Cost to Vehicle No :SJE3613S

Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 7,749.04
		Add GST @ 7%	542.43
		Total Amount Payable	<u>S\$ 8,291.47</u>

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND TWO HUNDRED NINETY ONE AND CENTS FORTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd

*Aliyah*

AUTHORISED SIGNATURE

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Admin L*  
*2/5 25/11/21.*  
*05 Days.*

*total: 449288*

*L/S: 3.6K*

*3.6K*