



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200153

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 07/01/2022
Reference CC4/FCI21012037/Epa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMX 2059M

Insured Veh. YP 1483C

Claim No. D21003262MFCV

Policy No.

Accident Date 23/11/2021

Inspection Date 30/11/2021

Description	Total
Survey Inspection	342.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	342.00
GST (7%)	23.94
Grand Total	365.94

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21012037/Epa3q2	
			Date: 07/01/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 1483C	Veh. Inspected	SMX 2059M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D21003262MFCV	Excess (\$)	0.00	
Assign From	ESTHER	Assign Date	26/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	INFINITI Q50	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JN1BCAV37Z0590103	Colour	WHITE	
Odometer	10520 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	BRIDGESTONE	5 mm	
L/H Front Tyre	225/50 R18	BRIDGESTONE	5 mm	
R/H Rear Tyre	225/50 R18	BRIDGESTONE	5 mm	
L/H Rear Tyre	225/50 R18	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2021	Inspection Date	30/11/2021	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 2059M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FACE -RR BUMPER (SN)	DENTED	1,283.50	1,155.15
7	CLIP BUMPER REAR (SN)	NECESSARY	30.80	27.72
1	BUMPER REAR RH BRACK (SN)	NOT NECESSARY	58.40	-
1	BRACKET -BUMPER RR RH (SN)	NOT NECESSARY	58.40	-
1	BUMPER REAR LH BRACK (SN)	NOT NECESSARY	58.40	-
1	BRACKET -BUMPER RR LH (SN)	NOT NECESSARY	58.40	-
1	REINF-BUMPER RR(SN)	NOT NECESSARY	910.20	-
1	TOW COVER (SN)	NOT NECESSARY	37.60	-
3	REATINER -BUMPER (SN)	NOT NECESSARY	190.80	-
4	SENSOR ASSY (SN)	SHORTED (1 PCS ONLY)	1,002.80	225.63
4	BRACKET SONAR RR -Q5 (SN)	NECESSARY (1 PCS ONLY)	313.60	70.56
2	DIFFUSER ASSY (SN)	NOT NECESSARY	200.80	-
1	BODY PANEL SEALANT (SN)	NOT NECESSARY	955.20	-
1	ADHESIVE SEALER FL2 (SN)	NOT NECESSARY	709.60	-
			5,868.50	1,479.06
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER ,REAR REINFORCEMENT ,ETC.		1,500.00	800.00
	TO SPRAY REAR BUMPER ,REAR REINFORCEMENT .		1,500.00	800.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		498.00	498.00
			3,498.00	2,098.00
GRAND TOTAL			9,366.50	3,577.06
RECOMMENDED COST OF REPAIRS				3,577.06

Report Ref No. CC4/FCI21012037/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMX 2059M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMX 2059M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMX 2059M

RE-INSPECTION

