



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFY 148E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (SN)	DEFORMED	3,268.00	3,268.00
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	273.00	-
1	REAR BUMPER SPOILER (SN)	NOT NECESSARY	479.00	-
1	REAR BUMPER SECURING STRIP (SN)	NOT NECESSARY	223.00	-
2	REAR BUMPER CLOSING ELEMENT-LH/RH (SN)	NOT NECESSARY	162.00	-
1	REAR BUMPER REINFORCEMENT BEAM (SN)	NOT NECESSARY	1,012.00	-
2	REAR BUMPER SEAL-LH/RH (SN)	NOT NECESSARY	28.00	-
2	REAR BUMPER GUIDE SECTION OUTER-LH/RH (SN)	NOT NECESSARY	66.00	-
2	REAR BUMPER GUIDE SECTION INNER-LH/RH (SN)	NOT NECESSARY	106.00	-
2	REAR BUMPER GUIDE PROFILE-LH/RH (SN)	NOT NECESSARY	134.00	-
1	REAR BUMPER GUIDE SECTION-CENTER (SN)	NOT NECESSARY	106.00	-
2	REAR BUMPER HODING STRAP-LH/RH (SN)	NOT NECESSARY	126.00	-
2	REAR PARKING AID SENSOR (NPA)(SN)	NOT NECESSARY	-	-
4	REAR PARKING AID SENSOR SEAL RING (SN)	NOT NECESSARY	6.00	-
2	EXHAUST CHROME TRIM-LH/RH (SN)	NOT NECESSARY	1,136.00	-
1	SUNDRIES (SN)	NOT NECESSARY	250.00	-
			7,375.00	3,268.00
	<b><u>LABOUR</u></b>			
	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION.		360.00	360.00
	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		1,200.00	800.00
	TO RESPRAY REAR BUMPER.		1,000.00	800.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			2,752.00	2,152.00
<b>GRAND TOTAL</b>			<b>10,127.00</b>	<b>5,420.00</b>



RECOMMENDED COST OF REPAIRS			5,420.00
-----------------------------	--	--	----------

Report Ref No. CS/SMO21012046/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.