

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0960/2021/JT  
**DATE** : 29-Nov-21  
**WIP** : 55682

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 3/12/21**

**YOUR INSURED VEH NO : YL 1183 P**

**SOMPO INSURANCE SINGAPORE PTE LTD**

50 Raffles Place

#05-01/06 Singapore Land Tower

Singapore 048623

Attn: Motor Claims Dept

**Tel: 6461 6555 Fax 6221 3147**

**OWNER'S NAME** : MS WONG PEI PEI (HUANG PEIPEI)  
**ADDRESS** : 55A EDGEDALE PLAINS  
#03-16  
SINGAPORE 828680  
**TELEPHONE** : HP +65 94506869  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 1800095997-03  
**VEHICLE NO** : **SFY 148 E**  
**MODEL CODE** : AUDI A6 1.6 TFSI S TRONIC  
**MODEL YEAR** : 10/8/2018  
**ENGINE NO** : CYG 023818  
**CHASSIS NO** : WAUZZZ4G4JN047199  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 26-Nov-21  
**PLACE OF ACCIDENT** : ESSO EXIT PETROL KIOSK

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFY 148 E**

|                             |                                                    |     |    | DAMAGED PARTS & PRICES |                  |
|-----------------------------|----------------------------------------------------|-----|----|------------------------|------------------|
| S/N                         | PARTS DESCRIPTION                                  | QTY |    | S/NETT                 | REMARKS          |
| 1                           | REAR BUMPER <i>del d</i>                           | 1   | \$ | 3,268.00               | ✓                |
| 2                           | REAR BUMPER FIXING PARTS <i>3 new</i>              | 1   | \$ | 273.00                 | +                |
| 3                           | REAR BUMPER SPOILER                                | 1   | \$ | 479.00                 | +                |
| 4                           | REAR BUMPER SECURING STRIP ?                       | 1   | \$ | 223.00                 | ?                |
| 5                           | REAR BUMPER CLOSING ELEMENT - LH / RH <i>2 new</i> | 2   | \$ | 162.00                 | +                |
| 6                           | REAR BUMPER REINFORCEMENT BEAM                     | 1   | \$ | 1,012.00               | +                |
| 7                           | REAR BUMPER SEAL - LH / RH ?                       | 2   | \$ | 28.00                  | ?                |
| 8                           | REAR BUMPER GUIDE SECTION OUTER - LH / RH          | 2   | \$ | 66.00                  | +                |
| 9                           | REAR BUMPER GUIDE SECTION INNER - LH / RH          | 2   | \$ | 106.00                 | +                |
| 10                          | REAR BUMPER GUIDE PROFILE - LH / RH                | 2   | \$ | 134.00                 | +                |
| 11                          | REAR BUMPER GUIDE SECTION - CENTER <i>1 new</i>    | 1   | \$ | 106.00                 | +                |
| 12                          | REAR BUMPER HODING STRAP - LH / RH                 | 2   | \$ | 126.00                 | +                |
| 13                          | REAR PARKING AID SENSOR <i>new</i>                 | 2   |    | TBC                    | +                |
| 14                          | REAR PARKING AID SENSOR SEAL RING <i>2 new</i>     | 4   | \$ | 6.00                   | +                |
| 15                          | EXHAUST CHROME TRIM - LH / RH                      | 2   | \$ | 1,136.00               | +                |
| 16                          | SUNDRIES ?                                         | 1   | \$ | 250.00                 | ?                |
| <b>TOTAL SPARE PARTS</b>    |                                                    |     | :  | \$                     | <b>7,375.00</b>  |
| <b>TOTAL LABOUR CHARGES</b> |                                                    |     | :  | \$                     | <b>2,752.00</b>  |
| <b>GRAND TOTAL</b>          |                                                    |     | :  | \$                     | <b>10,127.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFY 148 E**

| S/N                         | NATURE OF JOBS                                                                                            |        | ESTIMATED<br>CHARGES    | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|-----------------------------------------------------------------------------------------------------------|--------|-------------------------|-------------------------------|
| 1                           | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.                         | S/N \$ | 360.00                  | ✓                             |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | <del>1,200.00</del> 800 |                               |
| 3                           | TO RESPRAY REAR BUMPER.                                                                                   | \$     | <del>1,000.00</del> 800 |                               |
| 4                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                            | S/N \$ | 192.00                  | ✓                             |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                           | :      | <b>\$ 2,752.00</b>      |                               |



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian Lij

SURVEYED DATE

: 30/11/21

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not authorised, 03 days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT