



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0960/2021/JT
DATE : 29-Nov-21
WIP : 55682

Veron.
\$5420.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 3/12/21
YOUR INSURED VEH NO : YL 1183 P

SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623
Attn: Motor Claims Dept
Tel: 6461 6555 Fax 6221 3147

OWNER'S NAME : MS WONG PEI PEI (HUANG PEIPEI)
ADDRESS : 55A EDGEDALE PLAINS
#03-16
SINGAPORE 828680
TELEPHONE : HP +65 94506869
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800095997-03
VEHICLE NO : SFY 148 E
MODEL CODE : AUDI A6 1.6 TFSI S TRONIC
MODEL YEAR : 10/8/2018
ENGINE NO : CYG 023818
CHASSIS NO : WAUZZZ4G4JN047199
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BCO / ALLAN WU
ACCIDENT DATE : 26-Nov-21
PLACE OF ACCIDENT : ESSO EXIT PETROL KIOSK



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFY 148 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>del d</i>	1 S	3,268.00	✓
2	REAR BUMPER FIXING PARTS <i>3 pc</i>	1 S	273.00	+
3	REAR BUMPER SPOILER	1 S	479.00	+
4	REAR BUMPER SECURING STRIP <i>Not Rec</i>	1 S	223.00	×
5	REAR BUMPER CLOSING ELEMENT - LH / RH <i>3 pc</i>	2 S	162.00	+
6	REAR BUMPER REINFORCEMENT BEAM	1 S	1,012.00	+
7	REAR BUMPER SEAL - LH / RH <i>Not Rec</i>	2 S	28.00	×
8	REAR BUMPER GUIDE SECTION OUTER - LH / RH	2 S	66.00	+
9	REAR BUMPER GUIDE SECTION INNER - LH / RH	2 S	106.00	+
10	REAR BUMPER GUIDE PROFILE - LH / RH	2 S	134.00	+
11	REAR BUMPER GUIDE SECTION - CENTER	1 S	106.00	+
12	REAR BUMPER HODING STRAP - LH / RH	2 S	126.00	+
13	REAR PARKING AID SENSOR <i>rec</i>	2	TBC	+
14	REAR PARKING AID SENSOR SEAL RING <i>3 pc</i>	4 S	6.00	+
15	EXHAUST CHROME TRIM - LH / RH	2 S	1,136.00	+
16	SUNDRIES <i>Not Rec</i>	1 S	250.00	×
TOTAL SPARE PARTS		:	\$ 7,375.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	
GRAND TOTAL		:	\$ 10,127.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND REMARKS (OK) = APPROVED. REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1163
EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFY 148 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	✓ ✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	300 ✓
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00	300 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 2,752.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Adam Lj
: 30/11/21
:
:
: we authorised, 03 days
: *h.f.*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT