



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBW 777Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	ENGINE UNDER COVER (WCP)	CRACKED	290.00	290.00
1	FRONT BUMPER UNDER COVER (WCP)	CRACKED	185.00	185.00
1	ENGINE TURBO COOLER (WCP)	PUNCTURE	485.00	485.00
1	ENGINE TURBO COOLER COVER (WCP)	DENTED	25.00	25.00
1	AIR-CON CONDENSER (WCP)	BENT	585.00	585.00
1	RADIATOR (WCP)	BENT	405.00	320.00
1	RADIATOR FAN MOTOR (WCP)	SERVICEABLE	285.00	-
1	ENGINE FRT UNDER CROSS MEMBER (WCP)	BENT	755.00	290.00
1	WATER COOLER (WCP)	BROKEN	295.00	295.00
1	WATER COOLER BRACKET (WCP)	DISTORTED	20.00	20.00
1	ENGINE MOUNTING RH (ADDITIONAL) (WCP)	CRACKED	170.00	170.00
1	ENGINE MOUNTING LH (ADDITIONAL) (WCP)	CRACKED	150.00	150.00
1	ENGINE MOUNTING REAR (ADDITIONAL) (WCP)	CRACKED	165.00	165.00
1	ENGINE MOUNTING SUPPORT RH (ADDITIONAL) (WCP)	DISTORTED	210.00	210.00
1	ENGINE OIL STICK (ADDITIONAL) (WCP) (CRACKED)	NOT CONSISTENT WITH THE IMPACT	33.00	-
1	AIR FILTER DUCTING (ADDITIONAL) (WCP)	CRACKED	68.00	68.00
	COST PLUS 15%		618.90	488.70
			4,744.90	3,746.70
1	FRONT EXHAUST PIPE (SN)	BENT	1,240.00	600.00
	COST PLUS 15%		186.00	-
			1,426.00	600.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	RADIATOR COOLANT (4 LTRS) (SN)	NECESSARY	60.00	60.00
			60.00	60.00
<b><u>LABOUR</u></b>				
	TOWING.		50.00	50.00
	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, RADIATOR & MOTOR, GRILLE, UNDER COVER, TO REPAIR FRT SUPPORT PANEL & REALIGN THE SAME.		600.00	450.00

Report Ref No. CS/LPC21012047/Kqy3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS.		100.00	100.00
	REMOVE & REFIX ENGINE TURBO COOLER, FRT EXHAUST PIPE, ENGINE UNDER CROSS MEMBER, WATER COOLER & RESET SYSTEM.		600.00	400.00
			1,350.00	1,000.00
<b>GRAND TOTAL</b>			<b>7,580.90</b>	<b>5,406.70</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>5,406.70</b>

Report Ref No. CS/LPC21012047/Kqy3e2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.