



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS/LPC21012047/Kqy3e2

Date: 29/12/2022

Code: LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SBW 777Y
Policy No.	Z21VP05028230	Coverage (\$)	0.00
Claim No.	21/21/21/VP05/025193	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	29/11/2021

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD1173422N143145	Colour	METALLIC SILVER
Odometer	125439 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	MICHELIN	8 mm
L/H Front Tyre	225/40 R18	MICHELIN	8 mm
R/H Rear Tyre	225/40 R18	MICHELIN	8 mm
L/H Rear Tyre	225/40 R18	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/11/2021	Inspection Date	29/11/2021
Survey held at	CHENG HOE MOTOR PL 38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 SINGAPORE 757700		

5a. Remarks

A)THE MARKET VALUE IS S\$61,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**