

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SBW777Y
OD/Lonpac

M/S : LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
TEL: 62507388 FAX: 62963767
ATTN: Motor Claim Department

Claim No: ES2191152
Estimate No: ES2191152/YISHUN
Date: 29 Nov 2021
Policy No: Z21VP05028230
Veh Reg No: SBW777Y
Make/Model: MERCEDES BENZ
CLA180 (R18 BI)
Chassis No: WDD1173422N143145
Engine No: 27091030511146
Reg. Date: 05/01/2015

WS Ref: OD/LONPAC
Claim Type: Own Damage
Accident Date: 26/11/2021

Estimate Repair Cost to Vehicle No : SBW777Y

Pages: 1/1

Description	U/Price	Quantity	Cost <u>S\$</u>	Amount <u>S\$</u>
Cost Plus				
1 ENGINE UNDER COVER	290.00	1 PC	290.00	
2 FRONT BUMPER UNDER COVER	185.00	1 PC	185.00	
3 ENGINE TURBO COOLER	480.00	1 PC	480.00	
4 ENGINE TURBO COOLER COVER	25.00	1 PC	25.00	
5 AIR-CON CONDENSER	585.00	1 PC	585.00	
6 RADIATOR	405.00	1 PC	405.00	
7 RADIATOR FAN MOTOR	285.00	1 PC	285.00	
8 ENGINE FRT UNDER CROSS MEMBER	755.00	1 PC	755.00	
9 FRONT EXHAUST PIPE	1,240.00	1 PC	1,240.00	
10 WATER COOLER	295.00	1 PC	295.00	
11 WATER COOLER BRACKET	20.00	1 PC	20.00	
			4,565.00	
	Add 15%		684.75	5,249.75
Special Net				
12 RADIATOR COOLANT (4 LTRS)	60.00	1 UNIT	60.00	60.00
Labour				
13 TOWING	50.00	1 LA	50.00	
14 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, RADIATOR & MOTOR, GRILLE, UNDER COVER, TO REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	600.00	1 LA	600.00	
15 REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	100.00	1 LA	100.00	
16 REMOVE & REFIX ENGINE TURBO COOLER, FRT EXHAUST PIPE, ENGINE UNDER CROSS MEMBER, WATER COOLER & RESET SYSTEM	600.00	1 LA	600.00	
				1,350.00
			Total	S\$ 6,659.75
			Add GST @ 7%	466.18
			Total Amount payable	S\$ 7,125.93

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE