



A Subsidiary Of Autobacs Seven Co Ltd. Japan  
 8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)  
 Tel : 6702 1555 Fax : 6702 1444 (Co Reg. No. 201500047H)  
 Email : wendy@skauto.com.sg

TO	: AIG (SBA9933U)	DATE	: 24-Dec-21
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
<b>OWNER PARTICULAR</b>			
OWNER ID	: SXXXX051D		
<b>VEHICLE DETAILS</b>			
VEHICLE NO.	: SKW9093X	<i>Ceilia</i>	
MODEL / MAKE	: LEXUS ES250		
CHASSIS NO.	: JTHBJ1GG102105275		
<b>ACCIDENT DETAIL</b>			
DATE	: 8-Oct-21	CONTACT PERSON : MR. WINSON 91866680	
TIME	: 13:25HRS		

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>2nd</i>	1	\$ 1,035.00	\$ 1,035.00 <i>x</i>
2	FRONT BUMPER NUMBER PLATE GARNISH <i>1st</i>	1	\$ 145.00	\$ 145.00 <i>x</i>
3	FRONT BUMPER LOWER CENTER GRILL WITH CHROME MOLDING <i>ut.</i>	1	\$ 880.00	\$ 880.00 <i>✓</i>
4	FRONT BUMPER PARKING HOLDER (STICK ON) <i>2</i>	2	\$ 20.70	\$ 41.40 <i>+</i>
5	FRONT BUMPER TOP RUBBER SEAL (STICK ON) <i>1st</i>	1	\$ 93.50	\$ 93.50 <i>x</i>
6	FRONT BUMPER INNER SPONGE <i>1st</i>	1	\$ 122.00	\$ 122.00 <i>x</i>
TOTAL PRICE				\$ 2,316.90
LESS -10%				\$ (231.69)
SUB TOTAL PRICE				\$ 2,085.21

*880*  
*792*

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS SET <i>NE NW</i>	1	\$ 100.00	\$ 100.00 <i>x</i>
2	FRONT BUMPER NUMBER PLATE WITH CASING SET <i>2nd</i>	1	\$ 85.00	\$ 85.00 <i>+60</i>
3	FRONT BUMPER LOWER UNDER COVER CLIPS SET <i>2nd</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
4	FRONT SUPPORT PANEL TOP GARNISH CLIPS SET <i>1st</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
TOTAL				\$ 325.00

*60*

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 500.00	200	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 500.00	x 200.	
TO PERFORM LIGHTING & WIRING CHECK	\$ 150.00	x 30.	
TO DISMANTLE & REPLACED FRONT BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 120.00	50	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 380.00	x.	480.

TOTAL \$ 1,650.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 2,410.21  
 TOTAL LABOUR COST : \$ 1,650.00  
 TOTAL REPAIR COST : \$ 4,060.21

Admin Lj  
 P/p 28/11/21.  
 02 Days.

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS  
 REPAIR UNDER : PART BY PART OR LUMP SUM  
 DATE / TIME OF SURVEY :  
 SURVEYED BY / FROM :  
 CONTACT NUMBER :  
 EMAIL ADDRESS :  
 DATE / TIME OF RE-SURVEY :  
 EXCESS :

total: 1332  
 (P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: