

SPEEDWERKZ Pte Ltd

Bartley Biz Centre, 13 Kaki Bukit Road 4, #01-20 Singapore 417807

Tel: +65 9619 5936 / Email : info@speedwerkz.biz

To: Motor Claims Department

Date: 29/11/2021

Vehicle No: YP4426Z

Model: Mitsubishi Canter

Damaged Area: Rear Portion

Estimated Repair Cost For YP4426Z (Mitsubishi Canter)

QTY	Parts	Amount
1	Rear Crash Bar	\$ 1,286.00 x nn
2	Rear Crash Bar Bracket @ SGD 155.00	\$ 310.00 x nn
2	Taillamp @ SGD 486.00	\$ 972.00 x nn
2	Taillamp Bracket @ SGD 168.00	\$ 336.00 x nn
Parts Sum:		\$ 2,904.00
Parts Less 10% :		\$ 290.40
Parts Total:		\$ 2,613.60

Special Nett Items	
1	Rear hydraulic tailgate door
1 set	Rear hydraulic tailgate door reflective sticker
2	Rear hydraulic lifter pump assy (big) @ SGD 2,600.00
2	Rear hydraulic lifter pump assy (small) @ SGD 2,200.00
1	Sticker 60km/h
1	Rear Number Plate

		shifted
local repair 1000	\$ 7,800.00	Ry
	\$ 480.00	nn/200
1400	\$ 5,200.00	bl-
1200	\$ 4,400.00	bl-
	\$ 35.00	nn
	\$ 35.00	x nn
Special Nett Items Total:		\$ 17,950.00
		3800

Labour & Misc Charges	Description
* To Remove, Replace, Re-align & Install affected Rear Damaged Areas	
* To Putty, Prep & Re-spray on affected Rear Damaged Areas	
* To Repair & Align Rear Hydraulic Door	
* To Conduct a Check on All Affected Electrical Wirings	
* To Provide Rust Coatings on Affected Areas	

	Amount
\$	1,200.00 600
\$	800.00 x nn
\$	450.00 300
\$	80.00 30
\$	200.00 x nn
Labour Charges Total:	\$ 2,730.00 930

Tanfu 97495749

WP 29/11/21

1/2 Resurvey after repair

tanfu@lkhauto.com

06 days

3800

930

4730

1/2 3500

* 06 days

Parts Total:	\$ 2,613.60
Special Nett Items Total:	\$ 17,950.00
Labour Charges Total:	\$ 2,730.00
Total Cost Of Repair:	\$ 23,293.60
(Non-Inclusive of GST)	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: