



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMV 6409X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





TEL: 6256 3561 FAX: 6256 4315

The image shows a tablet screen displaying a diagnostic trouble code (DTC) list. The screen is titled "Diagnostic Trouble Code" and shows a list of codes and their descriptions. The codes are listed in a table-like format with columns for the code, description, and a status or count. The codes shown are C080177, C080178, C1344, C1343, and C1342. The descriptions are "4WD Pump Motor Control Circuit Open", "4WD Pump Motor Control Circuit Open", "Electric Parking Brake", "Brake System Malfunction", "Brake System Malfunction", "Brake System Malfunction", and "Brake System Malfunction". The status or count column shows "2", "2", "1", "1", and "1". The screen also has a search bar at the top and buttons for "Enter" and "Clear".

Code	Description	Status/Count
C080177	4WD Pump Motor Control Circuit Open	2
C080178	4WD Pump Motor Control Circuit Open	2
C1344	Electric Parking Brake	1
C1343	Brake System Malfunction	1
C1342	Brake System Malfunction	1