

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# SMV6409X

Accident Date : 26/11/2021

Location : CTE Tunnel (SLE)

TP SMRT.
Hui Zhen.

Model:

LEXUS NX300

(13/10/2020)

ERV: S\$107,510

3P:

SHC4860Y (First Cap)

JTJBARBZ905020723

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$	
1	1pc	Rear bumper Deformed 899.	1,410.30	✓		
2	10pcs	Rear bumper clips New		80.00	30	
3	2pcs	Rear bumper screw clips New		10.00	✓	
4	1pc	Rear bumper diffuser Crushed 561	1,135.40			
5	1pc	Rear bumper enforcement New	1,086.70	+		
6	2pcs	Rear reverse sensor 2 piece painted	1,276.20	600		
7	4pcs	Rear reverse sensor holder New	220.00	80		
8	1pc	Rear leg sensor New	780.80	+		
		Sub Total:	5,909.40	90.00	0.00	
		2140 S.N. 40	10%	0%	10%	
		1926.	After Less %:	5,318.46	90.00	0.00
		<u>Labour</u>				
1		To remove and refit rear damage parts		500.00	250	
2		To spray painting.		400.00	250	
3		To check for fault code and re set electrical system.		180.00	60	
4		To check wiring.		100.00	30	
		590	Sub Total:	1,180.00		
		Total:		6,588.46		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Chan San Choon
Director
DipEng, AAE MIM, MSAE(Aust)

Signature:

Date:

(P/P)

Adrian Lj
L/S 29/11/21.

03 Days

Supplementary: 351.80

total: 2907.50

(P/P)



8778 1999
24 hr accident call



2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# SMV6409X

Model: LEXUS NX300

Accident Date : 26/11/2021

(13/10/2020)

ERV: S\$107.510

Location : CTE Tunnel (SLE)

3P: SHC4860Y (First Cap)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear under cover <i>torn</i>	452.60	✓	
2		To do re-setting		350.00	180
		Sub Total:	452.60	350.00	0.00
			10%	0%	10%
		After Less %:	407.34	350.00	0.00
		Total:		757.34	

Chan
Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

191
171.90

S.N: 180



AL 8778 1999
24 hr accident call



Adnan Lj
02/12/21.

Supplementary: 351.90.