



AIG-OD CLAIM
SURVEY; 29/11/21
UKK-STEVE

VEHICLE NO : SLN 46C

MODEL : MIT/OUTLANDER 2.4 CVT

WIP : 17969

Material	:	\$	<u>6,569.64</u>
Labour	:	\$	<u>4,585.00</u>
Sub-Total	:	\$	<u>11,154.64</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>10,854.64</u>
GST 7%	:	\$	<u>759.82</u>
Grand Total	:	\$	<u>11,614.46</u>
Finalise By/Date : <u>Army on 31/12/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 06 WORKING DAYS + 2 days (wk. end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/11/2021	<table> <tr><td>Cust No/Name</td><td>KCV06103/Shaharum Bin Sulaiman</td></tr> <tr><td>Reg No/Reg Date</td><td>SLN46C*# / 18/05/2017</td></tr> <tr><td>Date In/Mileage</td><td>29/11/2021/ 77926</td></tr> <tr><td>Chassis/Package</td><td>JMYXTGF3WHZ000704 /@2</td></tr> <tr><td>Engine No</td><td>4B12SA1267</td></tr> <tr><td>Make/Model</td><td>MIT/OUTLANDER 2.4 CVT AWD (E44)</td></tr> <tr><td>Colour/Trim</td><td>W01 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV06103/Shaharum Bin Sulaiman	Reg No/Reg Date	SLN46C*# / 18/05/2017	Date In/Mileage	29/11/2021/ 77926	Chassis/Package	JMYXTGF3WHZ000704 /@2	Engine No	4B12SA1267	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)	Colour/Trim	W01 WHITE PEARL / BK BLACK
Cust No/Name	KCV06103/Shaharum Bin Sulaiman														
Reg No/Reg Date	SLN46C*# / 18/05/2017														
Date In/Mileage	29/11/2021/ 77926														
Chassis/Package	JMYXTGF3WHZ000704 /@2														
Engine No	4B12SA1267														
Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)														
Colour/Trim	W01 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	30/12/2021/ 16:14	BLE	884 / Lauro Songcuan	17969

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER, BONNET & LH FRONT FENDER, REPAIR LH FRONT DOOR				1125.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER, BONNET, LH FRONT FENDER & LH FRONT DOOR				1400.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00 ✓
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00 ✓
M SUNDRY SUPPLY BODY PANEL SEALANT				40.00 ✓
M SUNDRY APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS				160.00 ?
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB RESEAL FRONT NUMBER PLATE (OPC) MODEL:OUTLANDER				100.00 ✓
S SPECIALISTJOB SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & RED)				50.00 ✓
E PNT88000 REPLACE LH HEAD LAMP SUPPORT PANEL, FRONT INFORCEMENT, —————→ <i>Supp</i> LH TOP PANEL & LH WHEEL HOUSING				450.00 X
E PNT98000 SPRAY PAINT RH FRONT FENDER, LH "A" PILLAR, LH HEADLAMP SUPPORT AND —————→ <i>Supp.</i> FRONT RE-INFORCEMENT				1050.00 X
X EXC EXCESS				-300.00
X FACE,FR BUMPER ✓	1.00	810.00	23.00	623.70 ✓
X COVER,FR BUMPER ✓	1.00	281.00	23.00	216.37 ✓
X EXTENSION,FR BUMPER ?	1.00	428.00	23.00	329.56 ?
X GARNISH,FR BUMPER,LH ✓	1.00	78.00	23.00	60.06 ✓

This is not an official tax invoice.
This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/11/2021	<table> <tr><td>Cust No/Name</td><td>KCV06103/Shaharum Bin Sulaiman</td></tr> <tr><td>Reg No/Reg Date</td><td>SLN46C*# / 18/05/2017</td></tr> <tr><td>Date In/Mileage</td><td>29/11/2021/ 77926</td></tr> <tr><td>Chassis/Package</td><td>JMYXTGF3WHZ000704 /@2</td></tr> <tr><td>Engine No</td><td>4B12SA1267</td></tr> <tr><td>Make/Model</td><td>MIT/OUTLANDER 2.4 CVT AWD (E44)</td></tr> <tr><td>Colour/Trim</td><td>W01 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV06103/Shaharum Bin Sulaiman	Reg No/Reg Date	SLN46C*# / 18/05/2017	Date In/Mileage	29/11/2021/ 77926	Chassis/Package	JMYXTGF3WHZ000704 /@2	Engine No	4B12SA1267	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)	Colour/Trim	W01 WHITE PEARL / BK BLACK
Cust No/Name	KCV06103/Shaharum Bin Sulaiman														
Reg No/Reg Date	SLN46C*# / 18/05/2017														
Date In/Mileage	29/11/2021/ 77926														
Chassis/Package	JMYXTGF3WHZ000704 /@2														
Engine No	4B12SA1267														
Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)														
Colour/Trim	W01 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	30/12/2021/ 16:14	BLE	884 / Lauro Songcuan	17969

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BRACKET,FR BUMPER SIDE,LH ✓	1.00	18.00	23.00	13.86 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	220.00	23.00	169.40 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	112.00	23.00	86.24 ✓
X REINF,FR BUMPER SIDE,LH ?	1.00	60.00	23.00	46.20 ?
X HEADLAMP ASSY,LH ✓	1.00	2135.00	23.00	1643.95 ✓
X GRILLE ASSY,RADIATOR ✓	1.00	572.00	23.00	440.44 ✓
X HOOD ✓	1.00	980.00	23.00	754.60 ✓
X FENDER,FR LH ✓	1.00	622.00	23.00	478.94 ✓
X INSULATOR,FR FENDER,LH ✓	1.00	65.00	23.00	50.05 ✓
X SHIELD,FR WHEELHOUSE,LH ✓	1.00	164.00	23.00	126.28 ✓
X MOULDING,FR BUMPER,LH ✓	1.00	116.00	23.00	89.32 ✓
X MOULDING,FR WHEEL ARCH,LH ✓	1.00	199.00	23.00	153.23 ✓
X HOSE ASSY,HEADLAMP WASHER ?	1.00	135.00	23.00	103.95 ?
X ACTUATOR,HEADLAMP WASHER,L ?	1.00	212.00	23.00	163.24 ?
X COVER,HEADLAMP WASHER HOLE ?	1.00	53.00	23.00	40.81 ?
X REINFORCEMENT,FR BUMPER ?	1.00	505.00	23.00	388.85 ?
X PNL,HEADLAMP SUPT,UPR LH ?	1.00	58.00	23.00	44.66 ?
X HARNESS,FOG LAMP	1.00	130.00	23.00	100.10 X
X COVER,ENG ROOM UNDER,FR	1.00	349.00	23.00	268.73 X
X RIVET,FR BUMPER	6.00	5.00	23.00	23.10 X
X CLIP,FR BUMPER	10.00	4.00	23.00	30.80 X
X CLIP,RR BUMPER	20.00	3.00	23.00	46.20 X
X CLIP,ENG ROOM COVER X	10.00	2.00	23.00	15.40 ?
X HORN → Supp.	1.00	80.00	23.00	61.60 X

Z TEXT
 AIG - OD CLAIM
 SURVEY: STEVE (LKK) 29/11/2021
 DOA: 28/11/2021
 6 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	6,569.64	Nett	10,854.64
Labour	4,175.00	7% GST on	759.82
Standard Menu	0.00		
Specialist Job	150.00	Total Payable	11,614.46
Diagnostics Job	0.00		
Sundry/Others	-40.00		
Total(w/o GST)	10,854.64		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SLN 46 C

<u>Materials</u>		<u>Cost (\$)</u>	
1	Harness, Fog Lamp	130.00	— TN
2	Cover, Eng Room Under, FR	349.00	— BR
3	Rivet, FR Bumper (6 pcs)	30.00	— nec
4	Clip, FR Bumper (10 pcs)	40.00	— nec
5	Clip, RR Bumper (20 pcs)	60.00	— nec
6	Horn	80.00	— BT
		<u>689.00</u>	
23% Discount		<u>158.47</u>	
		<u>530.53</u>	
<u>Labour</u>			
1	Replace LH Head Lamp Support Panel, Front Reinforcement, LH Top Panel & Wheel Housing	450.00	✓
2	Spray Paint RH Front Fender, LH "A" Pillar, LH Head Lamp Support and Front Reinforcement	1,050.00	✓
		<u>1,500.00</u>	
Labour & Materials		2,030.53	
7% Gst		142.14	
Total		<u>2,172.67</u>	

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4658
FAX : 6567 5258

CAR NO: SLN46CWIP: 17969

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	EXTENSION. FR BUMPER	? / SUPP		✓ Pur	6405A197
2	REINFORCEMENT. FR BUMPER	? / SUPP		✓ BT	6400H568
3	REINFORCEMENT. FR BUMPER SIDE. LH	? / SUPP		✓ BT	6400D581
4	PANEL. HEADLAMP SUPPORT. UPR LH	? / SUPP		✓ BT	5256C259
5	HOSE ASSY. HEADLAMP WASHER	? / SUPP		✓ TN	8264A313
6	ACTUATOR. HEADLAMP WASHER LH	? / SUPP		✓ OR	8264A309
7	COVER. HEADLAMP WASHER HOLE	? / SUPP		✓ M15	8264A311WA
8	HORN	? / SUPP		✓ BT	8211A207
9	HARNES. FR BUMPER	? / SUPP		✓ TN	8518B146
10	COTER. ENGINE ROOM UNDER. FR	? / SUPP		✓ OR	5340B626
11	RIVET. FR BU (X6)	? / SUPP		✓ MK	MU001657
12	CLIP. FR BUM (X10)	? / SUPP		✓ MK	MR300300
13	CLIP. RR BUM (X20)	? / SUPP		✓ MK	MR288155
14	CLIP. ENGINE (X10)	? / SUPP		✓ MK	MU488006
15	MUDG ASSY w/cut FR LH	? / SUPP		✓ Cu1	7407A315
16		? / SUPP			
17	RESPRAY RHT FENDER	? / SUPP		✓	
18	IL LHT A PILLAR	? / SUPP		✓	
19	IL LHT SUPPORT / FR RINF	? / SUPP		✓	
20	Labour 1 day (LHT Top pd, under floor)	? / SUPP		✓	

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	6/12/21	Steve
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OUTLANDERSURVEYOR: STEVE

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW21091-00
V.C.I. Version	B179
Vehicle Information	GF3W XTMGZR 2017MY

Reg No: SLNAGC
Before using MUT-3x you want to check all the good

2021.12.23

2021.12.23

3/3

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW21091-00
V.C.I. Version	B179
Vehicle Information	GF3W 2017MY

Ref No: SH46C
 After use MIST-3x Not unit to Base all the good
 25th Dec
 2021.12.23

All DTCs

2021.12.23

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
	OSS	OSS_9588000B		No DTCs	
	CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
	EPB	EPB_4C080000		No DTCs	



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/Shaharum Bin Sulaiman</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLN46C / 18/05/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 77926</td></tr> <tr> <td>Chassis No</td><td>JMYXTGF3WHZ000704</td></tr> <tr> <td>Engine No</td><td>4B12SA1267</td></tr> <tr> <td>Make/Model</td><td>MIT/OUTLANDER 2.4 CVT AWD (E44)</td></tr> <tr> <td>Colour/Trim</td><td>W01 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	/Shaharum Bin Sulaiman	Reg No/Reg Date	SLN46C / 18/05/201	Date In/Mileage	/ 77926	Chassis No	JMYXTGF3WHZ000704	Engine No	4B12SA1267	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)	Colour/Trim	W01 WHITE PEARL / BK BLACK
Cust No/Name	/Shaharum Bin Sulaiman														
Reg No/Reg Date	SLN46C / 18/05/201														
Date In/Mileage	/ 77926														
Chassis No	JMYXTGF3WHZ000704														
Engine No	4B12SA1267														
Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)														
Colour/Trim	W01 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	29/11/2021/ 11:38	BLE	261 / Edwin Caina	17969			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000		1 1/2						2250.00
RENEW FR BUMPER , BONNET , LHF FENDER & FR SUPPORT					2 1/2			1125
REPAIR RHF FENDER & LHF DOOR								
E PNT98000								2100.00
RESPRAY FR BUMPER , BONNET , FR SUPPORT , LHF FENDER , RHF FENDER & LHF DOOR					4 X	350		1400
E PNT88000								100.00
REMOVE & REFIT AC COND & RADIATOR								80.00
M SUNDRY								30.00
TOP UP AC GAS								
A 54900099								120.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								
A 10028901								50.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								120.00
SUPPLY FR NUMBER PLATE WITH CASING								
M SUNDRY								40.00
RESEAL FR WEEKEND NUMBER PLATE								
M SUNDRY								60.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								160.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								20.00
APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS					4 panel	(provide paint sctn agent)		
M SUNDRY								
Sundries								
M SUNDRY								
SUPPLY BODY KIT (SET)								
M FACE,FR BUMPER					1.00	810.00	23.00	623.70
M COVER,FR BUMPER					1.00	281.00	23.00	216.37
M EXTENSION,FR BUMPER					1.00	428.00	23.00	329.56
M GARNISH,FR BUMPER,LH					1.00	78.00	23.00	60.06
M BRACKET,FR BUMPER SIDE,LH					1.00	18.00	23.00	13.86

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Shaharum Bin Sulaiman
	Reg No/Reg Date	SLN46C / 18/05/201
	Date In/Mileage	/ 77926
	Chassis No	JMYXTGF3WHZ000704
	Engine No	4B12SA1267
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	29/11/2021/ 11:38	BLE	261 / Edwin Caina	17969
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET,FR BUMPER SIDE,RH	X	1.00	18.00	23.00	13.86
M GARNISH,FR BUMPER SIDE	?	1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE	- mis	1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE	- mis	1.00	112.00	23.00	86.24
M REINFORCEMENT,FR BUMPER	?	1.00	0.00	23.00	
M REINFORCEMENT,FR BUMPER	?	1.00	135.00	23.00	103.95
M REINF,FR BUMPER SIDE,LH	?	1.00	60.00	23.00	46.20
M REINF,FR BUMPER SIDE,RH	?	1.00	69.00	23.00	53.13
M REINFORCEMENT,FR BMRP SIDE	?	2.00	22.00	23.00	33.88
M HEADLAMP ASSY,LH	- BR	1.00	2135.00	23.00	1643.95
M LAMP ASSY,FOG,FR	?	1.00	224.00	23.00	172.48
M GRILLE ASSY,RADIATOR	- BR	1.00	572.00	23.00	440.44
M COVER,HEADLAMP SUPT PANEL	?	1.00	50.00	23.00	38.50
M COVER,FR BUMPER	?	1.00	25.00	23.00	19.25
M BRACKET,RADIATOR GRILLE,LH	?	1.00	13.00	23.00	10.01
M BRACKET,RADIATOR GRILLE	?	1.00	10.00	23.00	7.70
M HOOD	- DD	1.00	980.00	23.00	754.60
M HINGE,HOOD,LH	X	1.00	68.00	23.00	52.36
M HINGE,HOOD,RH	X	1.00	68.00	23.00	52.36
M CLIP,HOOD INSULATOR	X	9.00	3.00	23.00	20.79
M WEATHERSTRIP,HOOD	X	1.00	41.00	23.00	31.57
M WEATHERSTRIP,HOOD	X	1.00	40.00	23.00	30.80
M TAPE,TAILGATE	X	4.00	4.00	23.00	12.32
M LATCH,HOOD	X	1.00	76.00	23.00	58.52
M FENDER,FR LH	- DD	1.00	622.00	23.00	478.94
M INSULATOR,FR FENDER,LH	- CRU	1.00	65.00	23.00	50.05
M SHIELD,FR WHEELHOUSE,LH	- BR	1.00	164.00	23.00	126.28
M CLIP,ENG ROOM COVER	X	8.00	2.00	23.00	12.32
M MOULDING,FR BUMPER,LH	X	1.00	116.00	23.00	89.32
M MOULDING,FR BUMPER,RH	X	1.00	116.00	23.00	89.32
M MOULDING,FR WHEEL ARCH,LH	- RC	1.00	199.00	23.00	153.23
M MOULDING,FR WHEEL ARCH,RH	X	1.00	199.00	23.00	153.23
M HOSE ASSY,HEADLAMP WASHER	?	1.00	135.00	23.00	103.95

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/Shaharum Bin Sulaiman</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLN46C / 18/05/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 77926</td></tr> <tr> <td>Chassis No</td><td>JMYXTGF3WHZ000704</td></tr> <tr> <td>Engine No</td><td>4B12SA1267</td></tr> <tr> <td>Make/Model</td><td>MIT/OUTLANDER 2.4 CVT AWD (E44)</td></tr> <tr> <td>Colour/Trim</td><td>W01 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	/Shaharum Bin Sulaiman	Reg No/Reg Date	SLN46C / 18/05/201	Date In/Mileage	/ 77926	Chassis No	JMYXTGF3WHZ000704	Engine No	4B12SA1267	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)	Colour/Trim	W01 WHITE PEARL / BK BLACK
Cust No/Name	/Shaharum Bin Sulaiman														
Reg No/Reg Date	SLN46C / 18/05/201														
Date In/Mileage	/ 77926														
Chassis No	JMYXTGF3WHZ000704														
Engine No	4B12SA1267														
Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)														
Colour/Trim	W01 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	29/11/2021/ 11:38	BLE	261 / Edwin Caina	17969
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M ACTUATOR, HEADLAMP WASHER, L		1.00	212.00	23.00	163.24
M COVER, HEADLAMP WASHER HOLE		1.00	53.00	23.00	40.81
M PANEL, HEADLAMP SUPPORT, UPR		1.00	230.00	23.00	177.10
M PNL, HEADLAMP SUPT, UPR LH		1.00	58.00	23.00	44.66
M LLC 4L		1.00	26.00	23.00	20.02

Estimate

SURVEYOR NAME: Steve (LKK) 29/11/21, 3.11pmSURVEYOR SIGNATURE: OD-M ALDATE: EXPRS-?REMARKS: P/P
By Bal sy
5 dys

Confirm & accepted by

7% GST on	Nett 11965.29	11,965.29 837.57
Total Payable		12,802.86

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.