



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Shaharum Bin Sulaiman
	Reg No/Reg Date	SLN46C / 18/05/201
	Date In/Mileage	/ 77926
	Chassis No	JMYXTGF3WHZ000704
	Engine No	4B12SA1267
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	29/11/2021/ 11:38	BLE	261 / Edwin Caina	17969			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2250.00
RENEW FR BUMPER , BONNET , LHF FENDER & FR SUPPORT								
REPAIR RHF FENDER & LHF DOOR								
E PNT98000								2100.00
RESPRAY FR BUMPER , BONNET , FR SUPPORT , LHF FENDER , RHF FENDER & LHF DOOR								
E PNT88000								100.00
REMOVE & REFIT AC COND & RADIATOR								
M SUNDRY								80.00
TOP UP AC GAS								
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								50.00
SUPPLY FR NUMBER PLATE WITH CASING								
M SUNDRY								120.00
RESEAL FR WEEKEND NUMBER PLATE								
M SUNDRY								40.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								60.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								160.00
APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS								
M SUNDRY								20.00
Sundries								
M SUNDRY								
SUPPLY BODY KIT (SET)								
M FACE,FR BUMPER					1.00	810.00	23.00	623.70
M COVER,FR BUMPER					1.00	281.00	23.00	216.37
M EXTENSION,FR BUMPER					1.00	428.00	23.00	329.56
M GARNISH,FR BUMPER,LH					1.00	78.00	23.00	60.06
M BRACKET,FR BUMPER SIDE,LH					1.00	18.00	23.00	13.86

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Shaharum Bin Sulaiman
	Reg No/Reg Date	SLN46C / 18/05/201
	Date In/Mileage	/ 77926
	Chassis No	JMYXTGF3WHZ000704
	Engine No	4B12SA1267
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	29/11/2021/ 11:38	BLE	261 / Edwin Caina	17969
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET,FR BUMPER SIDE,RH		1.00	18.00	23.00	13.86
M GARNISH,FR BUMPER SIDE		1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE		1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE		1.00	112.00	23.00	86.24
M REINFORCEMENT,FR BUMPER		1.00	0.00	23.00	
M REINFORCEMENT,FR BUMPER		1.00	135.00	23.00	103.95
M REINF,FR BUMPER SIDE,LH		1.00	60.00	23.00	46.20
M REINF,FR BUMPER SIDE,RH		1.00	69.00	23.00	53.13
M REINFORCEMENT,FR BMRP SIDE		2.00	22.00	23.00	33.88
M HEADLAMP ASSY,LH		1.00	2135.00	23.00	1643.95
M LAMP ASSY,FOG,FR		1.00	224.00	23.00	172.48
M GRILLE ASSY,RADIATOR		1.00	572.00	23.00	440.44
M COVER,HEADLAMP SUPT PANEL		1.00	50.00	23.00	38.50
M COVER,FR BUMPER		1.00	25.00	23.00	19.25
M BRACKET,RADIATOR GRILLE,LH		1.00	13.00	23.00	10.01
M BRACKET,RADIATOR GRILLE		1.00	10.00	23.00	7.70
M HOOD		1.00	980.00	23.00	754.60
M HINGE,HOOD,LH		1.00	68.00	23.00	52.36
M HINGE,HOOD,RH		1.00	68.00	23.00	52.36
M CLIP,HOOD INSULATOR		9.00	3.00	23.00	20.79
M WEATHERSTRIP,HOOD		1.00	41.00	23.00	31.57
M WEATHERSTRIP,HOOD		1.00	40.00	23.00	30.80
M TAPE,TAILGATE		4.00	4.00	23.00	12.32
M LATCH,HOOD		1.00	76.00	23.00	58.52
M FENDER,FR LH		1.00	622.00	23.00	478.94
M INSULATOR,FR FENDER,LH		1.00	65.00	23.00	50.05
M SHIELD,FR WHEELHOUSE,LH		1.00	164.00	23.00	126.28
M CLIP,ENG ROOM COVER		8.00	2.00	23.00	12.32
M MOULDING,FR BUMPER,LH		1.00	116.00	23.00	89.32
M MOULDING,FR BUMPER,RH		1.00	116.00	23.00	89.32
M MOULDING,FR WHEEL ARCH,LH		1.00	199.00	23.00	153.23
M MOULDING,FR WHEEL ARCH,RH		1.00	199.00	23.00	153.23
M HOSE ASSY,HEADLAMP WASHER		1.00	135.00	23.00	103.95

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Shaharum Bin Sulaiman
	Reg No/Reg Date	SLN46C / 18/05/201
	Date In/Mileage	/ 77926
	Chassis No	JMYXTGF3WHZ000704
	Engine No	4B12SA1267
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	29/11/2021/ 11:38	BLE	261 / Edwin Caina	17969

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M ACTUATOR, HEADLAMP WASHER, L	1.00	212.00	23.00	163.24
M COVER, HEADLAMP WASHER HOLE	1.00	53.00	23.00	40.81
M PANEL, HEADLAMP SUPPORT, UPR	1.00	230.00	23.00	177.10
M PNL, HEADLAMP SUPT, UPR LH	1.00	58.00	23.00	44.66
M LLC 4L	1.00	26.00	23.00	20.02

Estimate

SURVEYOR NAME : _____

SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

Confirm & accepted by

	Nett	11,965.29
7% GST on	11965.29	837.57
Total Payable		12,802.86

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.