

ASS REC. BY: TC Lim

REF:

CC4/AIG21012063/Bea3Ashen

ASSIGNMENT

From: _____ Date: 29/11/2021

Estimated Cost: _____

OD / ☒ / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMP 1941Pat Workshop m/s Dean Autoproof 160 Sin Ming Dr #01-14

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 69,000/2

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRSW

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMP 1941P Yr Regn: 12/9/2019Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Fit 1.3 GF c.c. 1317Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 220354 T/Radio: Insured / Std / NI / NAEng/No: L13B3934213C/No: GK33419722Gen. Cond: Good / Fair / Poor / BurntSteering: ☒ / Jammed / Leaked / Burnt or _____Brake: ☒ / Jammed / Leaked / Burnt or _____Modi: Nil / STD / STD A/Rim or _____Tyre Size: F: 175/70/14R: 175/70/14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ or _____

Front

Rear

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 24/11/2021 D.O.I. 29/11/2021Survey held at Dean AutoproDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range : <u>4,000/2 - 5,000/2</u>
	Recommended cor.: <u>\$4227.28 on Part by Part basis</u>
	MV <u>69,000/2</u>
	PV <u>25,902/2</u>
	NV <u>43,096/2</u>

TC Lim
6/2/2022

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ 1)
☐ : Interview (\$ 1)
☐ : Tech. Invs (\$ 1)
☐ : Weekend (\$ 1)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Rep. Format:

Lump Sum / L.B.T. ()

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SMP 1941 P**

Model : Honda Fit

Year : 2019

Chassis No : GK33419722

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

2019

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 1,085.20	\$ 779.20 1,085.20
2	Tailgate logo	1	\$ 86.20	\$ 86.20
3	Tailgate emblem 'Fit'	1	\$ 83.40	\$ 28.50 83.40
4	Tailgate inner lock	1	\$ 310.50	\$ 197.40 310.50
5	Tailgate inner lock striker	1	\$ 48.90	\$ NN 48.90
6	Tailgate weatherstrip	1	\$ 186.20	\$ 92.30 186.20
7	Tailgate inner trim board	1	\$ 486.00	\$ 241.20 486.00
8	Tailgate inner handle	1	\$ 56.20	\$ NN 56.20
9	Tailgate outer garnish	1	\$ 263.20	\$ NN 263.20
10	Tailgate windscreen moulding	1	\$ 132.60	\$ 104.90 132.60
11	Rear bumper	1	\$ 976.40	\$ 592.70 976.40
12	Rear bumper side retainer	2	\$ 25.70 87.50	\$ 51.40 175.00
13	Rear bumper bracket	2	\$ 75.60	\$ 151.20
14	Rear bumper centre garnish	1	\$ 103.00	\$ 97.00 103.00
15	Rear bumper side garnish	2	\$ 286.40	\$ NN 572.80
16	Rear end panel	1	\$ 865.70	\$ SVC 865.70
17	Rear end panel top garnish	1	\$ 186.50	\$ 60.80 186.50
18	Spare tyre panel	1	\$ 881.70	\$ NN 881.70
19	Spare tyre panel top board	1	\$ 250.00	\$ NN 250.00
20	Spare tyre panel insulator	1	\$ 188.60	\$ NN 188.60
21	Taillamp	2	\$ 376.20 686.00	\$ 376.20 1,372.00
22	Taillamp lower bracket	2	\$ 85.00	\$ NN 170.00
			Parts Sub Total :	\$ 2621.60 8,631.30
			Discount :	\$ 524.32 1,726.26
			PARTS TOTAL :	\$ 6,905.04

20%

2097.28

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Tailgate sealant	1	\$ 100.00	\$ 30.00 100.00
3	Tailgate inner trim board clips	1	\$ 50.00	\$ 30.00 50.00
4	Tailgate outer garnish clips	1	\$ 50.00	\$ 30.00 50.00
5	Tailgate windscreen clips	1	\$ 50.00	\$ 20.00 50.00
6	Tailgate windscreen sealant	1	\$ 100.00	\$ 30.00 100.00
7	Tailgate windscreen primer and cleaner	1	\$ 80.00	\$ 80.00
8	Tailgate windscreen seal	1	\$ 60.00	\$ 20.00 60.00
9	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
10	Rear bumper centre garnish clips	1	\$ 50.00	\$ 50.00
11	Rear bumper side garnish clips	2	\$ 50.00	\$ 100.00
12	Rear number plate w/casing	1	\$ 80.00	\$ NN 80.00
13	Rear bumper reverse sensor	2	\$ 200.00	\$ 200.00 400.00
14	Rear end panel sealant	1	\$ 100.00	\$ 100.00
15	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00 50.00
16	Taillamp seal	RH 1	\$ 60.00	\$ 30.00 120.00
17	Taillamp clips	RH 1	\$ 50.00	\$ 20.00 100.00
SPECIAL NETT TOTAL :				\$ 1,620.00

470.00

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 80.00 150.00
2	R&R tailgate windscreen	\$ 120.00 250.00
3	R&R rear bumper reverse sensor	\$ 60.00 100.00
4	Check wiring	\$ 100.00
5	Upholstery	\$ 300.00
6	Panel beating	\$ 800.00 1,600.00
7	Rust proofing	\$ 200.00
8	Spray painting	\$ 600.00 1,600.00
LABOUR TOTAL :		\$ 4,300.00

1660.00

PARTS TOTAL : \$ 6,905.04
SPECIAL NETT TOTAL : \$ 1,620.00
LABOUR TOTAL : \$ 4,300.00

GRAND TOTAL : \$ 12,825.04

Parts 2097.28
SN 490.00
Labour 1660.00
4227.28

COR \$ 4227.28 on Part by Part basis

Rtina Mue

6/2/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Survey 29/11/2021
Ttina Mue
15 30hrs

Resurvey 30/11/2021
Ttina Mue
17 30hrs

Part by Part repair
Repair days 7