



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2108514

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 10/12/2021
Reference CC4/FCI21012067/R1pa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SG 5869R
Insured Veh. YM 9310G
Claim No. D21003299MFCV
Policy No.
Accident Date 24/11/2021
Inspection Date 29/11/2021

Description	Total
Survey Inspection	261.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	261.00
GST (7%)	18.27
Grand Total	279.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21012067/R1pa3q2	
			Date: 10/12/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 9310G	Veh. Inspected	SG 5869R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D21003299MFCV	Excess (\$)	0.00	
Assign From	ESTHER	Assign Date	29/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAN A95	c.c	10518	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WMAA95ZZXG7003548	Colour	GREEN	
Odometer	345047 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm	
L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm	
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm	
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/11/2021	Inspection Date	29/11/2021	
Survey held at	310 MANDAI ROAD			
Repairer	TOWER TRANSIT SINGAPORE PTE. LTD.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5869R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	CRACKED		
	OUTDOOR IP CAMERA WITH LENS ASSY		1,200.00	1,200.00
			1,200.00	1,200.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE:OUTDOOR IP CAMERA WITH LENS ASSY, CONFIGURATION, TESTING.		1,300.00	320.00
	TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS: NS REAR ACCESS DOOR ,SIDE ACCESS DOOR .		1,950.00	320.00
	SPRAY PAINTING :NS REAR ACCESS DOOR ,SIDE ACCESS DOOR.		1,280.00	640.00
			4,530.00	1,280.00
GRAND TOTAL			5,730.00	2,480.00
RECOMMENDED COST OF REPAIRS				2,480.00

Report Ref No. CC4/FCI21012067/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SG 5869R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SG 5869R

RE-INSPECTION

