ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	13:16HRS		
ACCIDENT DATE	24-Nov-21		
BUS CAPTAIN NAME	MUHAMMAD HAMZAH BI MOHD ZAINI		
THIRD PARTY CLAIM AGAINST	MS First Capital Insurance Ltd		

BUS REGISTRATION NUMBER	SG5869R
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	-	Total Cost
1	OUTDOOR IP CAMERA WITH LENS ASSY	1	\$	1,200.00
		7% GST	\$	84.00
		PARTS TOTAL COST	\$	1,284.00

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	T	OTAL COST
TO DISMANTLE & REPLACE :-		
OUTDOOR IP CAMERA WITH LENS ASSYCONFIGURATIONTESTING	\$	1,300.00
TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS :-		
NS REAR ACCESS DOORSIDE ACCESS DOOR	\$	1,950.00
SPRAY PAINTING :-		
NS REAR ACCESS DOORSIDE ACCESS DOOR	\$	1,280.00
SPRAY PAINTING \$640 PER PANEL 7% GST	\$	317.10
LABOUR CHARGES \$650 PER DAY LABOUR TOTAL CO.	ST \$	4,847.10

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4: NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

			DATE IN	
		DATE & TIME SURVEY		
			DATE OUT	
BUS TYPE (SD / DD)	DD		TOTAL NUMBER OF DAYS	
	LOSS OF USE COST		\$	2,000.00

SUMMARY			
SECTION NO.		COST	
1	\$	1,284.00	
2	\$	4,847.10	
3	-		
4	\$	2,000.00	
TOTAL	\$	8,131.10	

PAGE 2