

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0028315
Lee Lin Ze

Page 1 of 2
Your ref. TP-SJZ 1138A Sampo
Job No. 72371
Our ref. 21.11.23
Payment
Date 29/11/2021

Attn

Vehicle No SLZ 280D
Vehicle Model Honda Jazz
Accident on 27/11/2021

Not Notified
83421.25 3271.25
Accum After Pay
7 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Tailgate			
1.00	Pc	Rear bumper	480.00		480.00
4.00	Pcs	Rear bumper clips	150.00		150.00
1.00	Pc	Rear bumper side retainer LH	1.00		4.00
1.00	Pc	Tail lamp LH	12.00		12.00
1.00	Pc	Rear windscreen moulding	130.00		130.00
1.00	Pc	Rear H logo emblem	18.00		18.00
1.00	Pc	Rear Jazz emblem	12.00		12.00
1.00	Pc	Rear end panel	20.00		20.00
		<i>Tailgate weather strip</i>	330.00		330.00
		Total amount of parts supplied - S\$1,156.00	45.00		45.00
1.00		25% of parts supplied.	289.00		289.00
		Special nett item.			
1.00	Set	Rear reversing sensor with installation	200.00		200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和天铁修理。
还有先进的 SAICO Deluxe 喷漆烘炉。
services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0028315
Lee Lin Ze

Page 2 of 2
Your ref. TP-SJZ 1138A Somp
Job No. 72371
Our ref. 21.11.23
Payment
Date 29/11/2021

Attn

Vehicle No SLZ 280D
Vehicle Model : Honda Jazz
Accident on ... 27/11/2021

29/11/2021 11:15 (SOT)
27/11/2021 22:20 (SOT)
C/O: Singapore
C/O: Towards Ang Mo Kio (Before Whampoa exit)
Singapore

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Labour & Misc.					
1.00		To remove + refit rear windscreen	140.00		140.00 120
1.00		To supply sealant	40.00		40.00 ✓
1.00		Tuff coat	80.00		80.00 60
1.00		To remove + refit rear side trim board LH & RH, etc	120.00		120.00 100
1.00		To straighten rear body including cutting and welding, to knock dents on rear floor panel and renew of parts	900.00		900.00 800
1.00		To spray paint	600.00		600.00 ✓
Sub-Total					3581.25
GST 7.00%					3,525.00
Total					246 75
					S\$ 3,771 75

司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
还有先进的 SAICO Deluxe 喷漆烘炉。

services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles."