

來發 (明記) 摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No EST0028315
Lee Lin Ze

Page 1 of 2
Your ref. TP-SJZ 1138A Somp
Job No 72371
Our ref 21.11.23
Payment
Date 29/11/2021

Attn

Vehicle No SLZ 280D
Vehicle Model Honda Jazz
Accident on 27/11/2021

*Not Notified
U/Sing &
Return After Paym
7days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Tailgate	480.00		480.00
1.00	Pc	Rear bumper	150.00		150.00
4.00	Pcs	Rear bumper clips	1.00		4.00
1.00	Pc	Rear bumper side retainer LH	12.00		12.00
1.00	Pc	Tail lamp LH	130.00		130.00
1.00	Pc	Rear windscreen moulding	18.00		18.00
1.00	Pc	Rear H logo emblem	12.00		12.00
1.00	Pc	Rear Jazz emblem	20.00		20.00
1.00	Pc	Rear end panel	330.00		330.00
Total amount of parts supplied - S\$1,156.00			900.00		
1.00		25% of parts supplied:	289.00		289.00
		Special nett item:	600.00		
1.00	Set	Rear reversing sensor with installation	200.00		200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

公司擁有最先進的 CAROLINER MARK IV 機械，可提供給多種款式的車身及給予快速與準確的測量方式和大鐵修理。此外，還有先進的 SAICO Deluxe 噴漆烘爐。
Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support ally system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩吸有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

180 Sui Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128009-3
URB: 1994075920

ESTIMATE

EST. No EST0028315
Lee Lin Ze

ACCIDENT Page 2 of 2
Your ref TP-SJZ 1138A Sampo
Job No 72371
Our ref 21 11 23
Payment
Date 29/11/2021
Singapore

Attn

DETAILS OF OWN VEHICLE

Vehicle No SLZ 280D
Vehicle Model : Honda Jazz
Accident on ... 27/11/2021

SLZ280D

Quantity	Unit	Description	Unit price	Disc pct	Amount
		Labour & Misc.			
1.00		To remove + refit rear windscreen	140.00		140.00
1.00		To supply sealant	40.00		40.00
1.00		Tuff coat	80.00		80.00
1.00		To remove + refit rear side trim board LH & RH, etc	120.00		120.00
1.00		To straighten rear body including cutting and welding, to knock dents on rear floor panel and renew of parts	900.00		900.00
1.00		To spray paint	600.00		600.00
Sub-Total					3,525.00
GST 7.00%					246.75
Total					SS 3,771.75

司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
，还有先进的 SAICO Deluxe 喷漆烘炉。
services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles."