## MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 67484422 / 67454422 Fax: 6747- 6720 REG NO 200501102H

	Die 1	w	Quotation
India International Insurance Pte Ltd			: 20.12.2021
64 , Cecil Street # 04 - 05		VEH NO	: SLR3393J
IOB Building Singapore 049711			: Kia Cerato
	016 043711	DOA	: 26.11.2021
- A	6347 - 6100	YR REF	: SLX6006B
Fax:	6224 - 4174	CHI DAY SHEARING STEEL	
Attn: Motor Claim Dept (Pls arrange vehicle survey & check liability)			
RE:	ESTIMATE FOR ACCIDENT REPA	AIR SLR3393J (KIA CERATO	1
<u>Item</u>	Description	Qty	_Amt
NO	LIST ITEMS		
RETALOR	Rear Bumper Delad	1	688.20
1 2	Rear Bumper Side Holder - RH	nen 1	32.40
3	Rear Rumper Lower Garnish	1	347.50
4	Rear Bumper Lower Garnish Refle	ctor - RH W 1	89.60
5	Rear Bumper Reinforcement	GHEAL	342.30 <del>*</del> 78.40 <del>*</del>
6	Rear Bumper Reinforcement Stay	- RH \ 1	78.40
	1157.70		\$ 1,578.40
	1041.53	Less 10%	(157.84)
	10		\$ 1,420.56
	S/NET ITEMS		
1	Rear Bumper Clips Ker	7 0 1	30.00
2	Rear Bumper Clips Reverse Sensor	SO 1	280.00 🗶
2	11000100		
			310.00
		er tolorado	\$ 1,730.56
		Total parts	\$ 1,700.00
	LABOUR CHARCE		
	LABOUR CHARGE		
1	To knocking & pull out rear portion &	500.00 200	
2	To putty & spray up paint works		500.00 200
3	To check wiring	480	500.00 200 500.00 200 50,00 30.
4	To remove reverse sensor		100,00 50

## RE: ESTIMATE FOR ACCIDENT REPAIR SLR3393J (KIA CERATO)

5 To spray tuff coat

100.00

1,250.00

Grand Total

\$ 2,980.56

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

tolul: 1551.93 Hs. 1250.

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: