



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21012073/Uuf3n2	
			Date: 17/12/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	EL 76J	Veh. Inspected	SMP 4635D	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2103519/SYH	Excess (\$)	0.00	
Assign From	MELVIN YE YONG KANG	Assign Date	29/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4 TFSI (A)	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WAUZZZF45HA026818	Colour	RED	
Odometer	48818 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/11/2021	Inspection Date	30/11/2021	
Survey held at	Blk 15 KAKI BUKIT RD 4, BARTLEY BIZ CENTRE #01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	