

# IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800  
HP : 9748 9940 Shawn Tan Fax : 6346 7213  
Email: shawn7530@hotmail.com

1 Dec 2021

Vehicle No.: SKK 633 K

Model: MINI COOPER

| QTY | List Items                          | DESCRIPTION | AMT \$              |
|-----|-------------------------------------|-------------|---------------------|
| 1   | Front bonnet                        | DD          | \$ 1,450.00 1355.84 |
| 1   | Front bonnet insulator              | 11          | \$ 289.00 X         |
| 1   | Front bonnet insulator clip (1 set) | 11          | \$ 80.00 X          |
| 1   | Front bonnet lock                   | 11          | \$ 145.00 X         |
| 1   | Front bonnet logo                   | 11          | \$ 90.00 89.80      |
| 1   | Front headlamp -RH                  | CRO         | \$ 1,655.00         |
| 1   | Front headlamp chrome rim           | CRO         | \$ 385.00 145       |
| 1   | Front grille assy                   | 11          | \$ 485.00 X         |
| 1   | Front bumper                        | DD          | \$ 955.00 797.42    |
| 1   | Front bumper centre grille          | 11          | \$ 145.00 X         |
| 1   | Front bumper clip (1 set)           | 11          | \$ 80.00            |
| 1   | Front bumper fog lamp               | CRO         | \$ 355.00           |
| 1   | Front bumper lower garnish          | 11          | \$ 260.00           |
| 1   | Front bumper reinforcement          | 11          | \$ 440.00 X         |
| 2   | Front bumper side retainers         | 11          | \$ 116.00 X         |
| 1   | Front fender wheel arch garnish     | 11          | \$ 320.00           |
|     |                                     |             | \$ 7,250.00         |
|     |                                     |             | Less 10% \$ 725.00  |
|     |                                     |             | \$ 6,525.00         |

## Special Nett Items

|   |                           |    |                  |
|---|---------------------------|----|------------------|
| 1 | Front bonnet sticker "3M" | 11 | \$ 500.00 350.00 |
|   |                           |    | \$ 500.00        |

## S/N. Labour Charges

|   |                                               |                 |
|---|-----------------------------------------------|-----------------|
| 1 | To check wiring and reset headlamps focusing. | \$ 80.00 20     |
| 2 | To apply undercoating.                        | \$ 150.00 40    |
| 3 | Panel beating.                                | \$ 1,400.00 400 |
| 4 | To re-spray painting on the affected areas.   | \$ 1,200.00 400 |
|   |                                               | \$ 2,830.00     |

Grand Total : \$ 9,855.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-5027.76  
102  
P-4851.98  
S-N-350  
L-860  
5761.84