



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2202427

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 28/04/2022
Reference CC4/LPC21009430/Uea3q2-
1
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMR 644T
Insured Veh. 5025S
Claim No. 20/21/21/VC40/024928
Policy No. Z/20/VC40/109099-001
Accident Date 06/09/2021
Inspection Date 29/11/2021

Description	Total
Third Party Express Settlement	400.00
Less:AC2106518 DD 17/09/2021	-250.00
Subtotal	150.00
GST (7%)	10.50
Grand Total	160.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21009430/Uea3q2-1	
			Date: 28/04/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	5025S	Veh. Inspected	SMR 644T	
Policy No.	Z/20/VC40/109099-001	Coverage (\$)	0.00	
Claim No.	20/21/21/VC40/024928	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	29/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0323420	Colour	BLACK	
Odometer	116931 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	GLEDE	6 mm	
L/H Front Tyre	205/60 R16	GLEDE	6 mm	
R/H Rear Tyre	205/60 R16	GLEDE	6 mm	
L/H Rear Tyre	205/60 R16	GLEDE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/09/2021	Inspection Date	29/11/2021	
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 644T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR	TO REPAIR SEE LABOUR	1,260.50	-
1	FRONT DOOR SIDE MIRROR COVER	MISSING	112.10	112.10
1	FRONT DOOR SIDE MIRROR BASE	DAMAGED	560.90	560.90
1	FRONT DOOR SIDE MIRROR LIGHT	NOT NECESSARY	121.30	-
1	FRONT DOOR SIDE MIRROR GLASS	NOT NECESSARY	210.60	-
1	FRONT DOOR OUTER HANDLE	NOT NECESSARY	161.90	-
	LESS 20% DISCOUNT		-485.46	-134.60
			1,941.84	538.40
	<u>LABOUR</u>			
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS.		600.00	300.00
	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR .		450.00	200.00
			1,050.00	500.00
GRAND TOTAL			2,991.84	1,038.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				800.00

Report Ref No. CC4/LPC21009430/Uea3q2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMR 644T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMR 644T

RE-INSPECTION

