

ASS. REC. BY: Marcus

REF:

CC4/LPC21012077/Hgs348382-1**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orThe U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

) S + RS, SI

) Photos

) Others

TOTAL

21/1/14 1/5 x 800 confirmed with MR Lee

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

M/S LONPAC INSURANCE BHD

100 BEACH ROAD

#19-00 SHAW PLAZA

SINGAPORE 189702

50255

ESTIMATE

DATE : 30.11.2021

VEHICLE NO : SMR644T

MAKE/MODEL : MAZDA 3

ACC DATE : 06.09.2021

PARTICULAR		UNIT PRICE	AMOUNT
		S\$	S\$
<u>LIST PRICE</u>			
1	1 FRONT DOOR	1,260.50	1,260.50 X
2	1 FRONT DOOR SIDE MIRROR COVER	112.10	112.10
3	1 FRONT DOOR SIDE MIRROR BASE	560.90	560.90
4	1 FRONT DOOR SIDE MIRROR LIGHT	121.30	121.30 X
5	1 FRONT DOOR SIDE MIRROR GLASS	210.60	210.60 X
6	1 FRONT DOOR OUTER HANDLE	161.90	161.90 X
			2,427.30
		LESS 20%	485.46
			<u>1,941.84</u>

LABOUR CHARGES :

1	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	300	600.00
2	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	200	450.00
			<u>1,050.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL : 2,991.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-673
20%
538.40
500
1038.4
20%
830

Not Acknowledged
29/11/21
1/5 @ 800
2 days
Whys the other up
all the Asher