



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

KIA
Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
NG SWEE CHIA, EVON (HUANG RUIJIA, EVON) 604B TAMPINES AVENUE 9 #11-874 SINGAPORE 522604 Contact No	<tr> <td>Cust No/Name</td><td>LCV14729/NG SWEE CHIA, EVON (HUANG RUIJI</td></tr> <tr> <td>Reg No/Reg Date</td><td>SNC7463U / 12/11/202</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MN5121087</td></tr> <tr> <td>Engine No</td><td>G4FGMH710368</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G805 PE</td></tr> <tr> <td>Colour/Trim</td><td>B4U GRAVITY BLUE / WK SATURN BLACK</td></tr>	Cust No/Name	LCV14729/NG SWEE CHIA, EVON (HUANG RUIJI	Reg No/Reg Date	SNC7463U / 12/11/202	Date In/Mileage	/ 0	Chassis No	KNAF3416MN5121087	Engine No	G4FGMH710368	Make/Model	KIA/CERATO 1.6 A EX G805 PE	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK
Cust No/Name	LCV14729/NG SWEE CHIA, EVON (HUANG RUIJI														
Reg No/Reg Date	SNC7463U / 12/11/202														
Date In/Mileage	/ 0														
Chassis No	KNAF3416MN5121087														
Engine No	G4FGMH710368														
Make/Model	KIA/CERATO 1.6 A EX G805 PE														
Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV14729	CRDVCH	29/11/2021/ 16:33	BLC	442 / CocoLu	43092
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
E PNT88000 RENEW REAR BUMPER, BOOTLID, REPAIR REAR END PANEL	1.5 x 400			600	1200.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60	60.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS (photo)				300	300.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL	2 x 350			700	1050.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM					30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					120.00
M SUNDRY C&C LOGO					40.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION					40.00
M SUNDRY Sundry					20.00
M COVER-RR BUMPER	1.00	243.00	00.00		243.00
M COVER-RR BUMPER LWR	1.00	193.00	00.00		193.00
M COVER-RR BUMPER UNDER, LH	1.00	33.00	00.00		33.00
M LAMP ASSY-SIDE T/SIGNAL, LH	1.00	181.00	00.00		181.00
M LAMP ASSY-SIDE T/SIGNAL, RH	1.00	181.00	00.00		181.00
M BRACKET-RR BPR UPR MTG	1.00	84.00	00.00		84.00
M BEAM-RR BUMPER	1.00	318.00	00.00		318.00
M BRACKET-RR BEAM LWR, CTR	1.00	6.00	00.00		6.00
M BRACKET-RR BEAM LWR MTG	1.00	7.00	00.00		14.00
M ANTENNA ASSY-SMARTKEY	1.00	46.00	00.00		46.00
M STAY-RR BUMPER LH	1.00	65.00	00.00		65.00
M STAY-RR BUMPER RH	1.00	65.00	00.00		65.00
M BRACKET-ASSY RR BPR SIDE UPR, R	1.00	26.00	00.00		26.00
M BRACKET ASSY-RR BPR SIDE UPR, L	1.00	31.00	00.00		31.00
M TRIM ASSY-RR TRANSVERSE	1.00	41.00	00.00		41.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NG SWEE CHIA, EVON (HUANG RUIJIA, EVON) 604B TAMPINES AVENUE 9 #11-874 SINGAPORE 522604 Contact No	Cust No/Name	LCV14729/NG SWEE CHIA, EVON (HUANG RUIJI
	Reg No/Reg Date	SNC7463U / 12/11/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MN5121087
	Engine No	G4FGMH710368
	Make/Model	KIA/CERATO 1.6 A EX G805 PE
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV14729	CRDVCH	29/11/2021/ 16:33	BLC	442 / CocoLu	43092			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL ASSY-TRUNK LID	✓ DD			1.00	1297.00	00.00	1297.00
M	EMBLEM-KIA	✓ ML			1.00	38.00	00.00	38.00
M	EMBLEM-CERATO	✓ ML			1.00	28.00	00.00	28.00

Stern (LKK)
 29/11/21, 5.00p
 DD-MAL
 EXGR-?
 P/P
 8 days

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

ster. (LKK)
29/11/21, 5-7p

DD-MAL
EX-11-?
P/P

Estimate

8 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

7% GST on **Nett** 5,750.00
Total Payable **6,152.50**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the windscreen. You must also agree to pay full amount for removal of the windscreen.