



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 28.11.2021
Emailed : 17.12.2021, 4.40pm
Date survey : 29.11.2021

VEHICLE NO : SNC 7463 U
MODEL : KIA CERATO 1.6 A EX
WIP : 43092

Material	:	\$	<u>1,984.80</u>
Labour	:	\$	<u>3,980.00</u>
Sub-Total	:	\$	<u>5,964.80</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>5,964.80</u>
GST 7%	:	\$	<u>417.54</u>
Grand Total	:	\$	<u>6,382.34</u>
Finalise By/Date	:	<u>LOI / 17/12/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 29/11/2021	Cust No/Name	LCV14729/NG SWEE CHIA, EVON (HUANG RUIJI
	Reg No/Reg Date	SNC7463U / 12/11/2021
	Date In/Mileage	29/11/2021/ 642
	Chassis/Package	KNAF3416MN5121087
	Engine No	G4FGMH710368
	Make/Model	KIA/CERATO 1.6 A EX G805 PE
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	16/12/2021/ 16:59	BLC	260 / AiTing	43092			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, BOOT LID, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 600.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR								✓ 60.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS TO FACILITATE REPAIR								? 300.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOL TID, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 700.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUPPLY C&C LOGO								✓ 40.00
M SUNDRY APPLY SEALANT ON ACCIDENT PORTIONS								? 40.00
M SUNDRY SUNDRIES								✓ 20.00
E PNT88000 REPLACE REAR END PANEL, REPAIR LH REAR FENDER, & RH REAR FENDER → Supp.								800.00
E PNT98000 RESPRAY ON REAR END PANEL, LH REAR FENDER, & RH REAR FENDER → Supp.								1050.00
S SPECIALISTJOB SUPPLY ONE SET OF REVERSE SENSOR → Supp.								220.00
X	COVER-RR BUMPER				1.00	✓ 243.00	20.00	194.40
X	COVER-RR BUMPER LWR				1.00	✓ 193.00	20.00	154.40
X	COVER-RR BUMPER UNDER,LH				1.00	? 33.00	20.00	26.40
X	BEAM-RR BUMPER				1.00	? 318.00	20.00	254.40
X	BRACKET-RR BEAM LWR MTG				(2) 1.00	? 7.00	20.00	5.60
X	PANEL ASSY-TRUNK LID				1.00	✓ 1297.00	20.00	1037.60

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 29/11/2021	Cust No/Name	LCV14729/NG SWEE CHIA, EVON (HUANG RUIJI
	Reg No/Reg Date	SNC7463U / 12/11/2021
	Date In/Mileage	29/11/2021/ 642
	Chassis/Package	KNAF3416MN5121087
	Engine No	G4FGMH710368
	Make/Model	KIA/CERATO 1.6 A EX G805 PE
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	16/12/2021/ 16:59	BLC	260 / AiTing	43092		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	EMBLEM-KIA			1.00	✓ 38.00	20.00	30.40
X	EMBLEM-CERATO			1.00	✓ 28.00	20.00	22.40
X	PANEL ASSY-BACK → Supp.			1.00	324.00	20.00	259.20
Z	TEXT						
	AIG OD CLAIM.						
	DOA: 28.11.21						
	SURVEYOR STEVE LKK 29.11.21 8						
	POLICY NO : 7210137801 REPAIR 8 DAYS						
Pro Forma							
Guarantee Your Warranty, Maintain with Cycle & Carriage!							

Parts	1,984.80	Nett	5,964.80
Labour	3,660.00	7% GST on	417.54
Standard Menu	0.00		
Specialist Job	220.00	Total Payable	6,382.34
Diagnostics Job	0.00		
Sundry/Others	100.00		
Total(w/o GST)	5,964.80		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.




Exceptional Journeys

INSURANCE CO.: AIG

Supplementary Parts For Registration No.: SNC 7463 U

<u>Materials</u>		<u>Cost (\$)</u>
1	Panel assy-Back	324.00 ✓ DD
Total Materials		324.00
Less 20% discount		64.80
Total after discount		259.20
<u>Labour</u>		<u>Cost (\$)</u>
1	Replace rear end panel, repair LH rear fender, & RH rear fender	800.00 ✓
2	Respray on rear end panel, LH rear fender, & RH rear fender	1,050.00 ✓
3	Supply one set of reverse sensor	220.00 ✓
Total labour		2,070.00
Total amount		2,329.20
7% GST		163.04
Grand total		<u>\$ 2,492.24</u>

Thank You.
Yours faithfully


LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

WIP: 43092 (ADDITIONAL PARTS CHANGE)

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

SURVEYOR: Steve



CERATO/FORTE../2022/G 1.6 MPI..



VCI



Fault Code Searching

Rescan

Save



12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
i-TPMS	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0259

VCI Ver.

02.63

ECU Ver.

M-E-K-01-00-0199

OS Ver.

Android 10