

廣摩多廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBJ1507Y

No.	Qty	List Items	
1	1	Rear bumper	\$ 517.20 ✓
2	2	Rear bumper side clips	\$ 60.00 X
3	4	Rear bumper inner bracket	\$ 154.00 X
4	1 set	Rear bumper clips	\$ 40.00 ✓
5	1	RH taillamp <i>395.80</i>	\$ 577.20 X ✓
6	1	RH taillamp lower garnish	\$ 99.30 X
7	1	Rear tailgate	\$ 2,162.72 X
8	1	Rear tailgate centre "TOYOTA" logo	\$ 66.20 —
9	1	Rear tailgate LH "TOYOTA" emblem	\$ 24.00 —
10	1	Rear tailgate LH "HIACE" emblem	\$ 39.00 —
11	1	Rear tailgate top lock	\$ 289.70 X
12	1	Rear tailgate weatherstrip	\$ 391.20 X
13	1 set	Rear tailgate inner board clips	\$ 50.00 —
14	1	Rear end panel outer	\$ 580.10 X
			\$ 5,050.62
Less 25%			\$ 1,262.66
Total :			\$ 3,787.97

Special Nett Items

15	1 set	Rear windscreen sealant	\$ 80.00 X
16	1 set	Rear end panel sealant	\$ 80.00 X
17		Rear tailgate RH "7pax" sticker	\$ 15.00 —
18	1	Rear tailgate LH "70km/h" sticker	\$ 15.00 —
Total :			\$ 190.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,000.00 600
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 600
3	To remove, refit rear windscreen glass.	\$ 140.00 X
4	To check wirings and lightings.	\$ 40.00 15/
5	To remove, refit rear tailgate fittings.	\$ 80.00 X
6	To remove, refit rear upholstery and attachments.	\$ 120.00 X
7	To supply and apply anti rust treatment	\$ 90.00 X
Total :		\$ 2,470.00

Total Parts and Labour : \$ 6,447.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Notified
C/Pay @ 1800h
Running After Rain
4 days