

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 08102600I

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Notified
1/10/18
Return After Rain
4 days

REPAIR ESTIMATE FOR GBJ1507Y

No.	Qty	List Items	Part	Price	Notes
1	1	Rear bumper	\$	517.20	✓
2	2	Rear bumper side clips	\$	30.00	X
3	4	Rear bumper inner bracket	\$	36.25	X
4	1 set	Rear bumper clips	\$	40.00	✓
5	1	RH taillamp	\$	577.20	X
6	1	RH taillamp lower garnish	\$	99.30	X
7	1	Rear tailgate	\$	2,162.72	X
8	1	Rear tailgate centre "TOYOTA" logo	\$	66.20	✓
9	1	Rear tailgate LH "TOYOTA" emblem	\$	24.00	✓
10	1	Rear tailgate LH "HIACE" emblem	\$	39.00	✓
11	1	Rear tailgate top lock	\$	289.70	X
12	1	Rear tailgate weatherstrip	\$	391.20	X
13	1 set	Rear tailgate inner board clips	\$	50.00	✓
14	1	Rear end panel outer	\$	580.10	X
			\$	5,050.62	
			Less 25%	\$	1,262.66
			Total :	\$	3,787.97

Special Nett Items

15	1 set	Rear windscreen sealant	\$	80.00	X
16	1 set	Rear end panel sealant	\$	80.00	X
17		Rear tailgate RH "7pax" sticker	\$	15.00	✓
18	1	Rear tailgate LH "70km/h" sticker	\$	15.00	✓
			Total :	\$	190.00

Rear Reverse Sensor Ser 2005m

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,000.00	600
2	To putty and spray Paintings charges.	\$	1,000.00	600
3	To remove, refit rear windscreen glass.	\$	140.00	X
4	To check wirings and lightings.	\$	40.00	15/
5	To remove, refit rear tailgate fittings.	\$	80.00	X
6	To remove, refit rear upholstery and attachments.	\$	120.00	X
7	To supply and apply anti rust treatment	\$	90.00	X
Total :		\$	2,470.00	

Total Parts and Labour : \$ 6,447.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: