




Accident Reference & Bus No: **E/4027/2021 - SBS8347Z with SMT5037C**

Activated date: **Thu 25/11/2021 16:16**

Activated by: Seow Yong Hua <seowyh@sbstransit.com.sg>

Name of Surveyor: Guo Qiang
Company Name: LKK Auto
Date Surveyed: 30/11/2021

Replace 2X RH mid body panel
RH 2X wheel arc trim
Re vinyl purple & white.

Require

Resurvey 1 Date:

Resurvey 2 Date:

Final Endorsement by Surveyor:

Estimate for

- ☒ Parts cost: \$
- ☒ Contractor Labour cost: \$
- ☒ Workshop Labour cost: \$
- ☒ Advertisement Cost: \$ 0
- ☒ Repair period: 2 day

Guo Qiang
8880282
LKK

- ☒ Tow Cost: \$ 0
- ☒ Loss of use: \$
- ☒ Overheads: \$

LKK Auto Consultants hence notify the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (penalty) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaired

Signature:

Date: