

SKH2869A. 2018 March

Porsche Macan. 1984CC

TP Ching

WP1ZZZ9SZJLB06151

Veron.

Front Bumper torn 2985 ✓

Front Bumper Clips. New 50 ✓

Front Bumper Side Holder LH. ~~AP~~ New 278 X ✓

Front Bumper Air Guide LH. ^{wt} 259 ✓

Front Bumper Side Grille LH. ^{2 x} 731 X

Front Bumper Signal Lamp LH. ^{per} 349 X.

Headlamp LH. ^{crack} 5099 ✓

Bonnet Dented 3058 ✓

Bonnet Logo New 297 ✓

Bonnet Lock 2 288 X

Front LH Inner Shield ^{AP} New 369 X

Front LH Inner Shield Clips 30 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s), must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SKH2869A.

Front LH Wheel Rim. ^{Lt} ~~3120~~ 1500(SN)

Front LH Tyre ^{Not New} 600(SN) x

Front LH Shock Absorber ? 1624 x

Front LH Knuckle Arm. ^{Not New} 1890 x

Front LH Lower Arm. 1090 x

Front LH Wheel Hub ^{clw Bearing} 529. x

12026. S.N: 1500

10823.40

Panel Beating.

~~800~~ 600

Spray Painting.

~~700~~ 550

Wiring.

~~100~~ 30

To spray tuft coat.

1410

~~100~~ x.

To dismantle front undercarriage.

380 x

To perform wheel alignment.

~~150~~ 80

To perform diagnostic test. 11,333

~~250~~ 150

25,126

Total: 13733.40

L/s: 10.9K-
05 Days